

Inspection Photos

Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17

Location #: 322404



Photo # 7061 From entrance to location



Photo # 7062 Location



Inspection Photos

Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17

Location #: 322404



Photo # 7063 Location



Photo # 7064 Location



Inspection Photos

Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17

Location #: 322404



Photo # 7065 Location



Photo # 7066 Location



Inspection Photos
Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17
Location #: 322404



Photo # 7067 Location



Photo # 7068 Tank label contains inaccurate info/does not comply with CECMC rules

Inspection Photos

Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17

Location #: 322404



Photo # 7069 Open ended piping/available for entry by wildlife/wildlife hazard



Photo # 7070 Open ended piping/available for entry by wildlife/wildlife hazard

Inspection Photos

Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17

Location #: 322404



Photo # 7071 Open ended load line



Photo # 7072 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: VISION ENERGY LLC BALDY CREEK UNIT 1-17

Location #: 322404



Photo # 7073 Secondary containment is insufficient/does not comply with CECMC secondary containment rules. Secondary containment is also overrun with vegetation & compromised.



Photo # 7074 Secondary containment is insufficient/does not comply with CECMC secondary containment rules. Secondary containment is also overrun with vegetation & compromised.