

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/24/2024

Submitted Date:

11/02/2024

Document Number:

708904953

FIELD INSPECTION FORM

Loc ID 322436 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10770
Name of Operator: VISION ENERGY LLC
Address: P O BOX 370
City: IGNACIO State: CO Zip: 81137

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Vision		pbechtolt@maralexinc.com	
, Vision		mollieo@maralexinc.com	All Inspections
, Vision		mrinc20@maralexinc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
322436	LOCATION	AC			-	BALDY CREEK-FEDERAL-67S90W 20NWNE	AC

General Comment:

[CECMC Inspection Report Summary](#)
On 10/24/2024 at approximately 12:17 hours, I, Compliance Specialist, Wayne Smelser Attempted to conduct an on-site inspection at VISION ENERGY LLC BALDY CREEK FEDERAL 2-20 Pad. Location # 322436 in Garfield County Colorado. Location is within High Priority/Density/NSO/Black Bear Habitat areas. Unable to access pad, locked gate on lease road to location.

This is a summary of inspection report.

Location

Lease Road:

Type Access

comment: No access - Unable to access pad, locked gate on lease road to location.

Corrective ActionL

Date:

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 322436 Type: LOCATION API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Please refer to Lease Road for comments	smelserw	11/02/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708904954	Inspection 708904953 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6770934