

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/23/2024

Submitted Date:

10/28/2024

Document Number:

717000102**FIELD INSPECTION FORM**Loc ID 320071 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #225City: AURORA State: CO Zip: 80016**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccenforcement@state.co.us	<a href="#">For CA Matrix Inspection Routing</a>
,		randy.silver@state.co.us	
Espinosa, Bill		billespinosa30@yahoo.com	<a href="#">Inspections</a>
Condill, J.B.	(303) 680-4725	jbcrog@aol.com	<a href="#">All Inspections</a>
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202495	WELL	SI	12/01/2019	GW	001-07900	CHAMPLIN 485 AMOCO 1	SI

**General Comment:**[Routine inspection](#)

**Location**Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank NFPA placards are faded and need to be replaced		
Corrective Action:	Install sign to comply with Rule 605.g see photo#6 corrective action date 11/29/2024	Date:	11/29/2024

**Emergency Contact Number:**

Comment:	Adequate		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	OTHER		
Comment:	Stormwater management sediment and erosion control		
Corrective Action:	BMPs: Rule 1002 f(2)c. Corrective action date 11/30/2024	Date:	11/29/2024
Type	OTHER		
Comment:	Mechanical issues: Well head leaking at time of inspection		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. Corrective action Date 10/30/2024 see OPGAL imaging video.	Date:	10/30/2024
Type	DEBRIS		
Comment:	Debris around separators on facility location.		
Corrective Action:	Comply with Rule 606 corrective action date 11/15/2024 see photo #5	Date:	11/15/2024
Type	WEEDS		
Comment:	Weeds around well sight, with berms and on berms and in pit		
Corrective Action:	Comply with Rule 606 corrective action date 11/15/2024 see photos # 3, 6, 7 through 14. (looks like some weed mitigation has been performed it just needs to be finished)	Date:	11/15/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Submersible Pump	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical equipment		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	210	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	3	300 BBLS	STEEL AST		39.928294,-104.150803	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

**Wells Served By Facilities Above**

API Number
001-07900

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

--

Inspected Facilities

Facility ID: 202495

Type: WELL

API Number: 001-07900

Status: SI

Insp. Status: SI

Idle Well

Purpose: ☒ Shut In

☐ Temporarily Abandoned

Reminder:

Comment: SI

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 09/08/2022

Annual Brhd Completed? No

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<div>CECMC Inspection Report Summary</div> <div>On Thursday October 24th 2024 at approximately 11:00am. I, Inspector Chane Finkenbinder,</div> <div>Conducted an on-site Routine inspection / BMPs from ECMC DOC# 693505232 have not been addressed.</div> <div>Location: Champlin 485 Amoco #1</div> <div>Operator: Renegade oil and Gas Company.</div> <div>API#:05-001-07900</div> <div>County: Adams</div> <div>While there, I observed a shut in well site and production facility.</div> <div>During this inspection the following possible compliance issues were observed:</div> <div>Mechanical issues: Rule 605e Corrective action date 10/30/2024 See OPGAL gas imaging video.</div> <div>Weeds: Rule 606 Corrective action date of 11/15/2024 see photos # 3, 6, 7 through 14.</div> <div>BMPs: Rule 1002 f(2)c. Corrective action date of 11/29/2024 See photos # 7 through 12.</div> <div>Placards: Rule 605 Corrective action date of 11/29/2024 See photo # 6.</div> <div>I spoke with Bill Espinosa on 10/24/2024 at 11:45AM to inform the well head was leaking at time of inspection.</div> <div>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</div> <div>This is a summary of inspection report.</div>	finkenbc	10/28/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403972132	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6763225">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6763225</a>
717000111	Inspection photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6763217">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6763217</a>
717000112	OPGAL-VIDEO	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6763218">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6763218</a>