

Inspection Photos

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 35-94-6S-94W Pad

Location ID: 322314



Photo # 8657 From entrance to location



Photo # 8658 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 35-94-6S-94W Pad

Location ID: 322314



Photo # 8659 Location



Photo # 8660 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 35-94-6S-94W Pad

Location ID: 322314



Photo # 8661 Location



Photo # 8662 Dead weeds/debris

Inspection Photos

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 35-94-6S-94W Pad

Location ID: 322314



Photo # 3768 From inspection 708903514 conducted on 04/11/2024 - Unused equipment

Photo # 8663 Unused equipment

Inspection Photos

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 35-94-6S-94W Pad

Location ID: 322314



Photo # 3769 From inspection 708903514 conducted on 04/11/2024 - Unused equipment

Photo # 8664 Unused equipment