

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/04/2024

Submitted Date:

11/04/2024

Document Number:

708904967

FIELD INSPECTION FORM

Loc ID: 322314
Inspector Name: Smelser, Wayne
On-Site Inspection:
2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10550
Name of Operator: MUSTANG RESOURCES LLC
Address: P O BOX 13550
City: BAKERSFIELD State: CA Zip: 93389

Findings:

15 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
, Mustang		nwelch@vaqueroenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210256	WELL	PR	07/01/2024	GW	045-06012	RULISON FEDERAL 35-94-6S-94W	PR

General Comment:

[CECMC Inspection Report Summary](#)
On 11/04/2024 at approximately 11:41 hours, I, Compliance Specialist, Wayne Smelser
Conducted a follow up inspection at MUSTANG RESOURCES LLC RULISON FEDERAL 35-94-6S-94W Pad.
Location # 322314 in Garfield County Colorado.
Please refer to inspection 708903514 conducted on 04/11/2024, previous corrective action has not been completed.
Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area.
Location is approximately 272 yards from Porcupine Creek.
While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- Housekeeping - Unused equipment on location with a CA date of 05/11/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.
This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	No tank battery		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	<input type="text" value="911/1-888-291-8588"/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on location - extra meter house on location & equipment is not in use. Please refer to FORM 4 document # 403769842 Operator stated "A meter house has been staged on location for installation of telemetry equipment. Mustang will complete the installation no later than October 31,2024 as instrumentation and electrical team is available." At the time of this inspection meter house has not been hooked up/is unused equipment		
Corrective Action:	The storage or placement of equipment and supplies not necessary for use on location is prohibited.		Date: <u>05/11/2024</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type:	Gas Meter Run	# 2	corrective date
Comment:	1 meter house is not hooked up & is not in use/unused equipment, please refer to Housekeeping for CA		
Corrective Action:		Date:	

Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.		
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:	Well is not on plunger lift		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 210256 Type: WELL API Number: 045-06012 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well is not on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Light compaction in some areas
		Ditches				
		Compaction				
Other						Rill erosion starting to develop near meter house
		Gravel				Sparse
Gravel						Sparse to none in most areas
		Culverts				

Comment: [Rill erosion starting to develop near meter house](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Housekeeping for corrective action	smelserw	11/04/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708904968	Inspection 708904967 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6773111
708904969	Inspection 708904967 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6773113