

**Storm Water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 331-11 Pad**  
**Location ID: 335638**



**Location Overview: Location is within High  
Priority/Density/Black Bear Habitat areas.**

**Section/Township/Range: 11 6S94W**





**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 331-11 Pad**  
**Location ID: 335638**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 331-11 Pad**  
**Location ID: 335638**



**Photo # 7540 Failure to minimize erosion & transport of sediment/BMP's need maintenance**



**Photo # 7541 Failure to minimize erosion & transport of sediment/BMP's need maintenance**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 331-11 Pad**  
**Location ID: 335638**



**Photo # 7542 Failure to minimize erosion & transport of sediment/BMP's need maintenance**



**Photo # 7543 Sediment trap needs maintenance (S/SW corner of location near entrance to location)**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 331-11 Pad**  
**Location ID: 335638**



**Photo # 7544 Erosion & transport of sediment onto lease road/insufficient BMP's (approximately 2/10<sup>th</sup> of a mile from entrance to location)**



**Photo # 7545 Erosion & transport of sediment onto lease road/insufficient BMP's (approximately 2/10<sup>th</sup> of a mile from entrance to location)**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 331-11 Pad**  
**Location ID: 335638**



**Photo # 7546 Tunnel erosion & transport of sediment onto lease road/BMP's need maintenance (approximately 3/10th of a mile from entrance to location)**



**Photo # 7547 Tunnel erosion & transport of sediment onto lease road/BMP's need maintenance (approximately 3/10th of a mile from entrance to location)**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 331-11 Pad**  
**Location ID: 335638**



**Photo # 7548 Erosion & transport of sediment onto lease road/insufficient BMP's (approximately 5/10th of a mile from entrance to location)**



**Photo # 7549 Large amount of sediment buildup at hay bales /BMP's may need maintenance in near future (Off edge of lease road near entrance to location)**