

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/04/2024

Submitted Date:

11/04/2024

Document Number:

708303016

FIELD INSPECTION FORM

Loc ID 335220	Inspector Name: Morris, Matthew	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 10 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested																																								
Operator Information: ECMC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: 1058 COUNTY ROAD 215 City: PARACHUTE State: CO Zip: 81635				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE																																								
Contact Information: <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>, TEP</td> <td></td> <td>COGCCInspectionReports@terraep.com</td> <td></td> </tr> </table>					Contact Name	Phone	Email	Comment	, TEP		COGCCInspectionReports@terraep.com																																	
Contact Name	Phone	Email	Comment																																									
, TEP		COGCCInspectionReports@terraep.com																																										
Inspected Facilities: <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr> <td>210783</td> <td>WELL</td> <td>PR</td> <td>09/03/1987</td> <td>GW</td> <td>045-06541</td> <td>MOBIL W-17-27</td> <td>PR</td> </tr> <tr> <td>265918</td> <td>WELL</td> <td>PR</td> <td>01/20/2004</td> <td>GW</td> <td>045-09090</td> <td>PA 34-27</td> <td>PR</td> </tr> <tr> <td>273768</td> <td>WELL</td> <td>PR</td> <td>03/30/2005</td> <td>GW</td> <td>045-10276</td> <td>PA 534-27</td> <td>PR</td> </tr> <tr> <td>273769</td> <td>WELL</td> <td>PR</td> <td>04/26/2005</td> <td>GW</td> <td>045-10277</td> <td>PA 434-27</td> <td>PR</td> </tr> </tbody> </table>					Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	210783	WELL	PR	09/03/1987	GW	045-06541	MOBIL W-17-27	PR	265918	WELL	PR	01/20/2004	GW	045-09090	PA 34-27	PR	273768	WELL	PR	03/30/2005	GW	045-10276	PA 534-27	PR	273769	WELL	PR	04/26/2005	GW	045-10277	PA 434-27	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																					
210783	WELL	PR	09/03/1987	GW	045-06541	MOBIL W-17-27	PR																																					
265918	WELL	PR	01/20/2004	GW	045-09090	PA 34-27	PR																																					
273768	WELL	PR	03/30/2005	GW	045-10276	PA 534-27	PR																																					
273769	WELL	PR	04/26/2005	GW	045-10277	PA 434-27	PR																																					
General Comment: <p>CECMC Inspection Report Summary</p> <p>On 11/4/2024 at approximately 12:40, Compliance Inspector Matthew Morris conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/27SWSE at Location ID #335220 in Garfield County, Colorado.</p> <p>During the inspection, the following compliance issues were observed:</p> <p>1) Wildlife entry hazards at separators</p> <p>A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.</p>																																												

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970)285-9377

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 4		
Comment: Multiple wildlife entry points on separators.			
Corrective Action: Secure equipment to prevent wildlife entry.		Date:	11/10/2024
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: Chemical tank			
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: CataFlow heater			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	210783	Type:	WELL	API Number:	045-06541	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	265918	Type:	WELL	API Number:	045-09090	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	273768	Type:	WELL	API Number:	045-10276	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	273769	Type:	WELL	API Number:	045-10277	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Sediment Traps				
Gravel						
		Ditches				
		Check Dams				
		Culverts				
Compaction						
		Rip Rap				
		Gravel				
		Compaction				
Berms						
				Material Handling And Spill Prevention		

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708303017	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6773381