

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/29/2024

Submitted Date:

10/29/2024

Document Number:

715201147

FIELD INSPECTION FORM

Loc ID 324853 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 37230
Name of Operator: HALDE OIL INC
Address: 46321 HWY 24
City: BURLINGTON State: CO Zip: 80807

Findings:

- 7 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Shalberg, Greg	719-688-3547	gregshalberg@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213222	WELL	SI	05/01/2024	OW	061-06584	JAGEE 1	PA

General Comment:

SE Compliance Specialist Brian Welsh conducted a P&A Inspection
Well was plugged. Operator has 30 days to remove equipment from location and begin final reclamation

Location

Lease Road:

Type	Access		
comment:	Gravel road through farm ground		
Corrective Action		Date:	

Overall Good:

Emergency Contact Number:

Comment:	<input style="width: 80%;" type="text"/>	Date:	
Corrective Action:	<input style="width: 80%;" type="text"/>	Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:	Piping, valves and misc stuff laying around		
Corrective Action:	Comply with Rule 606	Date:	11/29/2024

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: FWKO	# 1				corrective date	
Comment:	FWKO on east side of oil tanks					
Corrective Action:	Remove from location to begin final reclamation process				Date:	11/29/2024

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	Open Top		38.509800,-102.395170	
Comment:	Fiberglass open top water tank on east side of location					
Corrective Action:	Remove from location to begin final reclamation process				Date:	12/04/2024

Paint

Condition	<input style="width: 80%;" type="text"/>
Other (Content)	
Other (Capacity)	210bbbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				

CRUDE OIL	2	300 BBLs	STEEL AST		38.509750,-102.395550
Comment: 2-Crude oil tanks					
Corrective Action: Remove from location to begin final reclamation process					Date: 11/29/2024
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No					
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 213222 Type: WELL API Number: 061-06584 Status: SI Insp. Status: PA

Cement

Cement Contractor

Contractor Name: HP Oilfield Services

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 4329/1350/900/366

Cement Volume (sx): 192 sxs

Good Return During Job: YES

Cement Type: Class A

Comment: HALDE WATER, HP OILFIELD SERVICES, CODELL WELL SERVICES. INSPECTOR WITNESSED - MIRU CODELL, RIH W/CICR TO 900'. MIRU HP, PUMP 50SXS THRU W/12SXS ON TOP. MIRU CODELL, POOH W/TBG. MIRU HP, BREAK CIRC W/14BBLS PUMP 130SXS W/CMT TO SFC.

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403974801	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6765707