

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/30/2024

Submitted Date:

10/30/2024

Document Number:

699506539

FIELD INSPECTION FORMLoc ID 452048 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10694

Name of Operator: PROVIDENCE OPERATING LLC DBA POCO

Address: 16400 DALLAS PARKWAY SUITE 400

City: DALLAS State: TX Zip: 75428

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Brown, Devon		dbrown@providence-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452346	WELL	PR	04/01/2024	OW	123-45536	Buford 33-8-4L	PR
452347	WELL	PR	04/01/2024	OW	123-45537	Buford 33-7-3L	PR
452348	WELL	PR	04/01/2024	OW	123-45538	Buford 33-6-2L	PR
452349	WELL	PR	04/01/2024	OW	123-45539	Buford 33-7-1L	PR
452350	WELL	PR	04/01/2024	OW	123-45540	Buford 33-8-2L	PR
452351	WELL	PR	04/01/2024	OW	123-45541	Buford 33-10-2L	PR
452352	WELL	PR	05/01/2024	OW	123-45542	Buford 33-10-4L	PR
452354	WELL	PR	05/01/2024	OW	123-45544	Buford 33-9-3L	PR
456062	WELL	PR	05/01/2024	OW	123-47338	Desha 4-10-2L	PR
456067	WELL	PR	05/01/2024	OW	123-47343	Desha 4-15-1	PR

General Comment:

There have been no changes to equipment on location since previous inspection.

Inspected Facilities

Facility ID: 452346 Type: WELL API Number: 123-45536 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 452347 Type: WELL API Number: 123-45537 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 452348 Type: WELL API Number: 123-45538 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 452349 Type: WELL API Number: 123-45539 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 452350 Type: WELL API Number: 123-45540 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 452351 Type: WELL API Number: 123-45541 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 452352 Type: WELL API Number: 123-45542 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 452354 Type: WELL API Number: 123-45544 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 456062 Type: WELL API Number: 123-47338 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 456067 Type: WELL API Number: 123-47343 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/24/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment

User

Date

At time of inspection location appears to be in compliance with ECMC rules.
At time of inspection weather conditions were cold, calm, overcast.

medinaj

10/30/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699506540	inspection pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6773553