

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/29/2024

Submitted Date:

11/04/2024

Document Number:

708201763

**FIELD INSPECTION FORM**

Loc ID: 312292    Inspector Name: Edwardson, Dylan    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 95620  
Name of Operator: WESTERN OPERATING COMPANY  
Address: 1165 DELAWARE STREET #200  
City: DENVER    State: CO    Zip: 80204

**Findings:**

- 7 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Waggoner, Kyle		kyle.waggoner@state.co.us	
JAMES, STEVEN D	(303) 893-2438	steve@westernoperating.com	
Fischer, Alex		alex.fischer@state.co.us	
Coleman, Chris		chris.coleman@state.co.us	
Heibel, Krystal		krystal.heibel@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
100311	PIT	AC			-	PROPST 2B	RI
221086	WELL	SI	05/01/2024	OW	075-09212	PROPST 2	RI
256303	PIT	AC			-	PROPST B-2	RI
312292	LOCATION	AC	05/09/2024		-	PROPST-611N53W 27NESE	RI

**General Comment:**

This is a follow-up Interim Reclamation and Stormwater Inspection for Location ID (312292) and to the previous FIR (doc #708201667) conducted on 09/30/2024.

Refer to Environmental FIR (doc #709100440) conducted on 10/29/2024 for additional information.

This location has an associated AOC with Order NO. (1V-870).

Refer to the photo-documentation of the observed compliance issues attached to this report. Any corrective action(s) and corrective action due dates from previous inspections that have not been addressed are still applicable.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Undesirable vegetation (kochia, russian thistle) was observed throughout the location including soil stockpiles and excavated areas. This was previously documented in FIR (doc #708201456) and does not appear to have been completed.		
Corrective Action:	Comply with Rule 606 and and manage undesirable vegetation. (Original CA Date: 08/13/2024).	Date:	08/13/2024

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 100311 Type: PIT API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 221086 Type: WELL API Number: 075-09212 Status: SI Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 256303 Type: PIT API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 312292 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Previous FIR (doc #708201667) documented that sediment transport may have occurred on the drainage northwest of the pit/salt kill excavation. It appears that the berm may have been breached resulting in the deposition of stormwater and sediment into the drainage. As the stormwater originated from the pit/salt kill excavation, it is considered E&P waste and as result, a reportable spill. It does not appear that a Form 19 has been submitted at the time of this report submission. Original CA remains.

Corrective Action: Report spill or release of E&P waste or produced fluids by submitting a Form 19. Remove free fluids and contact ECMC Remediation staff per Rule 912.b.(24 hours to remove free fluids. 24 hours for notification and 72 hours for Initial Form 19 Report.)

Date: 10/11/2024

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS In Process

Comment Previous FIRs documented that the excavated pit and salt kill areas, and stockpiled materials, were unstabilized with evidence of unconsolidated materials. Additionally, no liners were observed underneath the stockpiles of impacted materials from the pit or salt kill excavations.  
  
During this inspection, it was observed that the stockpiles within the excavated areas appeared to have been compacted and equipment tracked for short term stabilization. Further, the stockpiles near the wellhead/production facilities appeared to have had berms and sigange installed. Operator shall continue to monitor and manage stockpiled soils in compliance with Rule 1002.c.

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTRURBANCE MINIMIZATION Fail

Comment Disturbances resulting from excavation of the pit and the salt kill area remain evident. These disturbances have not been approved with a F27 work plan for the excavation of the pit or salt kill areas. The total disturbance area represents approx. 3.10 acres, with an excavated area of approx. 1.5 acres in total, and a combined stockpile quantity of approx. 6300 CY (approx. 0.75 acres).  
  
Additionally, it was observed that vehicle traffic is occurring outside of the established access road, near the Y intersection northeast of the location. Any vegetation outside of the original disturbance area that fails to recover/reestablish will require additional reclamation activities. Refer to attached inspection photos.

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1003b. Area no longer in use? Fail Production areas stabilized? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail

Production areas have been stabilized? \_\_\_\_\_

Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation Fail

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: It appears that some straw wattles have been reinstalled, however, they do not appear to be installed per good engineering practices and are not properly functioning (damaged/degraded). Other areas experiencing erosion degradation do not appear to have been repaired and/or stabilized. Additionally, there is evidence of sediment transport into the adjacent drainage on the northwestern portion of the pit excavation (refer to Environmental Sectional for additional) and near the western stockpile. Stormwater control measures remain inadequate for this location. Refer to attached inspection photos.

Corrective Action: Comply with Rule 1002.f.(2) to install BMPs in accordance with good engineering practices and repair erosion degradation.

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	256303	846025	

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708201775	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6773909">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6773909</a>