

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/30/2024

Submitted Date:

10/30/2024

Document Number:

708302988**FIELD INSPECTION FORM**

Loc ID 334769	Inspector Name: Morris, Matthew	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 8 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> ECMC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
, CAERUS		ecmc.inspections@qb-energy.com	

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
237	WELL	PR	01/15/2009	GW	045-15455	FEDERAL GARDNER 21-13BB (PK-21)	PR
238	WELL	PR	01/14/2009	GW	045-15456	FEDERAL SMITH 21-12 (PK-21)	PR
239	WELL	PR	10/14/2009	GW	045-15457	FEDERAL SMITH 21-12BB (PK-21)	PR
240	WELL	PR	09/01/2008	GW	045-15458	FEDERAL 21-11(PK-21)	PR
241	WELL	PR	01/17/2009	GW	045-15459	FEDERAL 21-11BB (PK-21)	PR
294	WELL	PR	09/01/2009	GW	045-15475	FEDERAL 21-15BB(PK-21)	PR
295	WELL	PR	08/30/2009	GW	045-15476	FEDERAL 21-10BB(PK-21)	PR
296	WELL	PR	08/28/2009	GW	045-15477	FEDERAL 21-10(PK-21)	PR

<b>General Comment:</b> <a href="#">CECMC Inspection Report Summary</a>  On 10/30/2024 at approximately 11:05, Compliance Inspector Matthew Morris conducted an on-site inspection at CAERUS PICEANCE LLC, FEDERAL GARDNER-67S95W/21NESW at Location ID #334769 in Garfield County, Colorado.  During the inspection, the following compliance issues were observed:  1) Wildlife entry hazard at Summit Midstream gas meter  A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.  This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.
--

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970)285-2615

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Concrete barriers		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Concrete barriers		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 8		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1		
Comment:	Summit Midstream Meter house door is open and poses a wildlife entry hazard.		
Corrective Action:	Secure equipment to comply with Rule 608.e.		Date: 11/05/2024
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 8		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					

**Paint**

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities						
Facility ID:	237	Type:	WELL	API Number: 045-15455	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	238	Type:	WELL	API Number: 045-15456	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	239	Type:	WELL	API Number: 045-15457	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	240	Type:	WELL	API Number: 045-15458	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	241	Type:	WELL	API Number: 045-15459	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	294	Type:	WELL	API Number: 045-15475	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	295	Type:	WELL	API Number: 045-15476	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	296	Type:	WELL	API Number: 045-15477	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						

Producing Well			
Comment:			
Corrective Action:			Date: <div></div>

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Compaction				
Compaction						
Ditches						
Gravel						
		Ditches				
Berms						
		Gravel				
				Material Handling And Spill Prevention		

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues. Unable to inspect all Stormwater BMPs due to snow cover.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403976810	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6767552">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6767552</a>
708302989	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6767549">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6767549</a>