



FORM
INSP

Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
10/28/2024
Submitted Date:
10/30/2024
Document Number:
713400433

FIELD INSPECTION FORM

Loc ID
335528

Inspector Name:
Popejoy, Dusty

On-Site Inspection ☐

2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

☐ THIS IS A FOLLOW UP INSPECTION

☒ FOLLOW UP INSPECTION REQUIRED

☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

27 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
ENERGY, QB		ecmc.inspections@qb-energy.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287149	WELL	SI	02/01/2024	GW	045-12895	PUCKETT 14A-24D	SI
287150	WELL	PR	05/01/2018	GW	045-12894	PUCKETT 14B-24D	PR
287151	WELL	PR	12/31/2008	GW	045-12893	PUCKETT 14C-24D	PR
287152	WELL	PR	12/31/2008	GW	045-12892	PUCKETT 14D-24D	PR
287153	WELL	SI	10/01/2023	GW	045-12891	PUCKETT 24A-24D	SI
287154	WELL	SI	12/01/2023	GW	045-12890	PUCKETT 24B-24D	SI
287155	WELL	SI	10/01/2023	GW	045-12889	PUCKETT 24D-24D	SI
287156	WELL	PR	12/31/2008	GW	045-12888	PUCKETT 24C-24D	PR

General Comment:

CECMC Inspection Report Summary

On 10/28/2024 at approximately 11:28 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection at QB Energy PUCKETT-66S97W/24SSW at Location ID # 335528 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

1. Housekeeping - Multiple loose barbed wire fencing/wildlife hazard with a CA date of 11/06/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Date Run: 11/6/2024 Doc [#713400433]

Page 1 of 7

Location

Lease Road:			
Type	Access		
comment:	Access		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-2615/911

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Multiple loose barbed wire fencing/wildlife hazard, refer to photos		
Corrective Action:	Comply with CECMC wildlife rules	Date:	11/06/2024
Type	DEBRIS		
Comment:	Refer to photos		
Corrective Action:		Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Pig station/Pipe fence		

Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe fence		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 1		
Comment:	Knock out drum		
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:	All Bradenhead valves are accessible		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Nitrogen tank		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
----------	---	----------	------	---------	--------	--

CONDENSATE	1	400 BBLs	HEATED STEEL AST			
Comment: Telemetry on tank						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Inadequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient				
Comment: Centralized containment						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	400 BBLs	STEEL AST			
Comment: Telemetry on tank						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient				
Comment: Centralized containment						
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities

Facility ID: 287149 Type: WELL API Number: 045-12895 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Last produced January 2024

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287150 Type: WELL API Number: 045-12894 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287151 Type: WELL API Number: 045-12893 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287152 Type: WELL API Number: 045-12892 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287153 Type: WELL API Number: 045-12891 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Last produced September 2023

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287154 Type: WELL API Number: 045-12890 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Last Produced November 2023

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287155 Type: WELL API Number: 045-12889 Status: SI Insp. Status: SI

Idle Well	
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned	Reminder: _____
Comment: <input type="text" value="Last produced September 2023"/>	
Corrective Action: <input type="text"/>	Date: <input type="text"/>

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: <input type="text" value="287156"/>	Type: <input type="text" value="WELL"/>	API Number: <input type="text" value="045-12888"/>	Status: <input type="text" value="PR"/>	Insp. Status: <input type="text" value="PR"/>
--	---	--	---	---

Producing Well	
Comment: <input type="text" value="Producing well"/>	
Corrective Action: <input type="text"/>	Date: <input type="text"/>

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Berms						
		Gravel				Sparse to none in most areas
Gravel						Sparse to none in most areas
		Berms				
		Ditches				
		Sediment Traps				
Compaction						

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403976814	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6767573
713400434	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6767572