

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/28/2024

Submitted Date:

10/28/2024

Document Number:

714201811

**FIELD INSPECTION FORM**

Loc ID 311325 Inspector Name: Santistevan, Brittani On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 8 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Tibbs, Dan	970-539-0664	Dtibbs@kpk.com	
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	<a href="#">all inspections.</a>
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241895	WELL	SI	06/01/2024	OW	123-09686	MUSICK-MCCLINTOCK 3	SI

**General Comment:**

[This is an audit of MUSICK-MCCLINTOCK #3 scout card and related documents followed by a field inspection.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	One tank does not display contents/capacity. See attached photos.		
Corrective Action:	Comply with Rule 605.h.	Date:	11/28/2024
Type	BATTERY		
Comment:	No sign displayed. See attached photo.		
Corrective Action:	Comply with Rule 605.e.	Date:	11/28/2024

**Emergency Contact Number:**

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

**Good Housekeeping:**

Type	WEEDS		
Comment:	overgrown vegetation on various areas of location. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	11/28/2024

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#			corrective date
Type: Bird Protectors	# 1			
Comment:	<input type="text"/>			
Corrective Action:				Date: <input type="text"/>
Type: Horizontal Heated Separator	# 1			
Comment:	<input type="text"/>			
Corrective Action:				Date: <input type="text"/>

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,	
Comment:	<input type="text"/>					
Corrective Action:						Date: <input type="text"/>

**Paint**

Condition	Adequate	
Other (Content)	<input type="text"/>	
Other (Capacity)	50 BBLs	
Other (Type)	<input type="text"/>	

<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment: <a href="#">Shares containment with other tanks.</a>						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	OTHER	STEEL AST		,	
Comment:						
Corrective Action:				Date:		
<u>Paint</u>						
Condition	Adequate					
Other (Content)	UNKNOWN					
Other (Capacity)	UNKNOWN					
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:				Date:		
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:				Date:		

**Inspected Facilities**

Facility ID: 241895 Type: WELL API Number: 123-09686 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments		
Comment	User	Date
ECMC Inspection Report Summary WEATHER CONDITIONS: cloudy, dry ground. On Monday, October 28, 2024 at approximately 1130, I, Inspector Brittani Santistevan, conducted an on-site inspection at MUSICK-MCCLINTONK #3 (KP Kauffman Company Inc), at location ID: 311325 in WELD COUNTY, Colorado. While there, I observed a shut-in facility. During this inspection the following possible compliance issues were observed: 1. It appears to be overgrown vegetation on various areas of location. Comply with Rule 606. (Corrective Action Date: November 28, 2024) See attached photo #3-8. 2. It appears to be no sign displayed at the tank battery. Install sign to comply with Rule 605.e. (Corrective Action Date: November 28, 2024) See attached photo #1. 3. It appears there is no contents/capacity displayed on one tank. Install sign to comply with Rule 605.h. (Corrective Action Date: November 28, 2024) See attached photo #2.  A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.	santistb	10/28/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403977076	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6767895">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6767895</a>
714201812	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6767888">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6767888</a>