

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/05/2024

Submitted Date:

11/07/2024

Document Number:

715201180

**FIELD INSPECTION FORM**

Loc ID 321944 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 88380  
Name of Operator: TINDALL OPERATING COMPANY  
Address: P.O. BOX 4507  
City: ENGLEWOOD State: CO Zip: 80155

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Tucker, Lee		rleetuck@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208639	WELL	SI	06/01/2024	GW	017-07574	UPR 1-25	PR

**General Comment:**

SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location and equipment  
Form 6N (403865498) has been approved. Expiration date of 2/7/25

**Location**

**Lease Road:**

Type	Access		
comment:	Trail through farm ground		
Corrective Action:			Date:

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Lease sign by electric panel		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by tank		
Corrective Action:			Date:

**Emergency Contact Number:**

Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 208639 Type: WELL API Number: 017-07574 Status: SI Insp. Status: PR

**Producing Well**

Comment: [Producing. Meter run is 615' E of wellhead on west side of CR 60](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715201184	wellhead photo	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6778525">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6778525</a>