


# Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 25-20 Pad

Location # 335236



Nov 6, 2024 at 10:24:12 AM  
CO



Nov 6, 2024 at 10:26:05 AM  
CO

Photo # 9184 From entrance to location

Photo # 9185 Location

# Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 25-20 Pad

Location # 335236



Photo # 9186 Location



Photo # 9187 Location

# Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 25-20 Pad

Location # 335236



Photo # 9188 Location



Photo # 9189 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 25-20 Pad

Location # 335236



Nov 6, 2024 at 10:34:07 AM  
CO



Nov 6, 2024 at 10:34:23 AM  
CO

Photo # 9190 Location

Photo # 9191 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 25-20 Pad

Location # 335236



Photo # 9192 Location



Photo # 9193 Open ended load line

## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 25-20 Pad

Location # 335236



Photo # 9194 Debris