

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/31/2024

Submitted Date:

11/01/2024

Document Number:

696206398

## FIELD INSPECTION FORM

 Loc ID 324475 Inspector Name: Trujillo, Aaron On-Site Inspection  2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**
 ECMC Operator Number: 10515  
 Name of Operator: GUNNISON ENERGY LLC  
 Address: 999 18TH STREET SUITE 1755N  
 City: DENVER State: CO Zip: 80202
**Findings:**

- 8 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		geops@oxbow.com	Inspection mail box
Katz, Aaron		aaron.katz@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278793	WELL	SI	12/01/2018	GW	051-06064	HOTCHKISS FEDERAL 12-89 17-13	RI
324475	LOCATION	AC			-	DGU Federal 1289 17-13 Pad	RI
436660	WELL	DG	09/01/2019	LO	051-06127	DGU Federal 1289 17-13 CS2	RI

**General Comment:**

On 10/31/2024, Western Reclamation Work Lead Trujillo inspected Gunnison Energy's DGU Federal 1289/17-13 Pad location in Gunnison County, Colorado.

The following compliance issues were observed during this inspection:

- Stockpile protections
- Excavations missing required fencing
- Final Reclamation requirements
- "As built" coordinate requirements

Refer to the Reclamation section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type			
Comment:	Multiple excavations observed throughout the Location related to facility closure operations- excavations have not been fenced pursuant to Rule 913.b.(5)B.i.		
Corrective Action:	Comply with Rule 913.b.(5)B.i Operator on site was provided notice of fencing requirements at excavations.		Date: 11/02/2024

<b>Equipment:</b>			corrective date
Type: Other	#		
Comment:	After review of well records and COGIS, it has been determined that the coordinates for well API 05-051-06064, including the "as drilled" coordinates, are incorrect.		
Corrective Action:	Submit correct coordinates for wells on the Location. Comply with Rule 216 for GPS/PDOP requirements.		Date: 11/08/2024

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 278793 Type: WELL API Number: 051-06064 Status: SI Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 324475 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 436660 Type: WELL API Number: 051-06127 Status: DG Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_ Fail \_\_\_\_\_

Comment **Multiple stockpiles associated with excavations observed throughout the Location. BMPs to protect the stockpiles from wind and water erosion, as well as to minimize sediment transport, have not been implemented.**

Corrective Action **Comply with Rules 1002.c and 1002.f- install or repair required stormwater and erosion control BMPs at the stockpiled soils stored on Location.**  
**Operator on site was provided notice of the stockpile protection requirements.** Date **11/02/2024**

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment:

Pursuant to Rule 1004.a, upon the plugging and abandonment of a well, all debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well. It was observed in this inspection that pipe/riser equipment on the northwest end of the Location has not been removed.

Pursuant to Form 6(s) 403899875, the only PR well on the Location (051-06064) was P&Ad 6/29/2024- all surface equipment was required to be removed by 9/29/2024

Corrective Action: **Comply with Rule 1004.a and removal all surface equipment from the Location.**

Date \_\_\_\_\_

Overall Final Reclamation

Well Release on Active Location

Multi-Well Location

**ECMC Comments**

Comment	User	Date
The well status for the DGU Federal 1289 #17-13 CS2 (API 05-051-06127) is "Drilling", with a status date of "9/1/2019". Form 4 #402834900 suggests that only the conductor was drilled and set, and that no further drilling had occurred. Including ECMC Area Engineer for notification purposes.	trujilloam	11/01/2024
Facility Closure operations in-process at time of inspection. See remediation project #36474 for additional details.	trujilloam	11/01/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403979833	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6770278">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6770278</a>
696206401	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6770273">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6770273</a>