

State of Colorado
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

ECMC RECEPTION

Receive Date:

10/31/2024

Document Number:

403977654

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 47120 Contact Person: Erik Mickelson
Company Name: KERR MCGEE OIL & GAS ONSHORE LP Phone: (970) 929-4306
Address: P O BOX 173779 Fax: ()
City: DENVER State: CO Zip: 80217-3779 Email: Erik_Mickelson@oxy.com

Identification Information

API Number: 05 - - ECMC Facility ID: 485209 Initial Form 19 or 27 Document number:
Facility Name: LIZZY Facility Number: 8-36HZ Facility Type: LOCATION
Location QtrQtr: SENE Section: 36 Township: 1N Range: 68W Meridian: 6
County: WELD Field Name:
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: Absaroka Solutions Agent Name: Jordan Fleming Title: Environmental Professional
Phone Number: 7202448469 Email: jordan.fleming@absarokasolutions.com

Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: ☐ Unlined ☐ Lined ☐ Fenced ☐ Netted**Sample Location Information:**

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 772245 Facility Name: Villani 228631 Facility Type: Domestic Well
Location: QtrQtr: SESE Sec: 25 Twp: 1N Range: 68W Meridian: 6
County Name: WELD Latitude: 40.018110 Longitude: -104.944020

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 123152 Document Name: Size of file in bytes: 13341 File Name: 2024_08_08_Villani 228631 Isotech NG4 ECMC.xlsx
SampleType: Matrix:
Facility ID: 772245 Sample ID: 663075 Sample Name: Villani 228631 Sample Date: 08/08/2024
Collection Point: Dom Matrix: WATER Pre Post: Voluntary Post drill
Project Number: Remediation Number: Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: ISOTECH Lab Sample ID: 933362

Batch ID: 123152		Document Name: Size of file in bytes: 13341		File Name: 2024_08_08_Villani 228631 Isotech NG4 ECMC.xlsx	
SampleType: _____			Matrix: _____		
Facility ID: 772245	Sample ID: 663074	Sample Name: Villani 228631		Sample Date: 08/08/2024	
Collection Point: Dom	Matrix: GAS	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 933362		

Batch ID: 123151		Document Name: Size of file in bytes: 11274		File Name: 2024_08_08_Villani 228631 Isotech SIW ECMC.xlsx	
SampleType: _____			Matrix: _____		
Facility ID: 772245	Sample ID: 663073	Sample Name: Villani 228631		Sample Date: 08/08/2024	
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 933356		

Batch ID: 123149		Document Name: Size of file in bytes: 25869		File Name: 2024_08_08_Villani 228631 SGS ECMC.xlsx	
SampleType: _____			Matrix: _____		
Facility ID: 772245	Sample ID: 663071	Sample Name: Villani 228631		Sample Date: 08/08/2024	
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA66289-1		

Batch ID: 123150		Document Name: Size of file in bytes: 11691		File Name: 2024_08_08_Villani 228631 Trip Blank SGS ECMC.xlsx	
SampleType: _____			Matrix: _____		
Facility ID: 772245	Sample ID: 663072	Sample Name: Villani 228631		Sample Date: 08/08/2024	
Collection Point: TB	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA66290-1		

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
772245	403977705	2024_08_08_Villani_228631_Wellhead_Loc.jpg	Photographs	JPG
772245	403977682	2024_08_08_Villani 228631 Isotech NG4.pdf	Analytical Laboratory Report	PDF
772245	403977706	2024_08_08_Villani_228631_Wellhead.jpg	Photographs	JPG
772245	403977697	2024_08_08_Villani 228631 SGS.pdf	Analytical Laboratory Report	PDF
772245	403977673	2024_08_08_Villani 228631 Isotech SIW.pdf	Analytical Laboratory Report	PDF
772245	403977707	2024_08_08_Villani_228631_Spigot_Loc.jpg	Photographs	JPG
772245	403977703	2024_08_08_Villani_228631_FS_ECMC.pdf	Field Data Report	PDF
772245	403977663	2024_08_08_Villani 228631 Trip Blank SGS.pdf	Analytical Laboratory Report	PDF
772245	403977709	2024_08_08_Villani_228631_PrePostPurge.jpg	Photographs	JPG
772245	403977708	2024_08_08_Villani_228631_Spigot.jpg	Photographs	JPG

Sample ECMC Well Related:

No Sample ECMC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	The data submitted by the operator can be accessed through COGIS data system.	11/08/2024
Total: 1 comment(s)		