

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/28/2024

Submitted Date:

11/07/2024

Document Number:

715201146

FIELD INSPECTION FORM

Loc ID: 321173 Inspector Name: Welsh, Brian On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 76175
Name of Operator: SANDLIN OIL CORP
Address: PO BOX 430
City: DACONO State: CO Zip: 80514-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 12 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Sandlin, Gary		SandlinOilCorporation@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259738	WELL	SI	05/01/2022	GW	009-06617	HEIRONIMUS 1	SI

General Comment:

SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location and equipment
Form 6N (403411823) has been Approved
Form 6A (403383668) has been Approved with a plug date of 12/31/27

Location

Lease Road:

Type	Access		
comment:	Access to location is farmed over		
Corrective Action			Date:

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Sticker on tank		
Corrective Action:			Date:

Emergency Contact Number:

Comment:		Date:
Corrective Action:		

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds across location need maintenance		
Corrective Action:	Comply with Rule 606		Date: 11/28/2024

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	corrective date
Gas Meter Run	# 0	Central meter sheds have been removed	
Corrective Action:			Date:
Pump Jack	# 1	Parkersburg unit	
Corrective Action:			Date:
Prime Mover	# 1	Arrow gas engine	
Corrective Action:			Date:
Vertical Separator	# 1	Vertical gas separator on south side of wellhead	
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		37.181830,-102.126820

Comment:	Water tank on south side of wellhead	Date:	
Corrective Action:		Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	150bbbs
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Berms are inadequate			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date: 11/28/2024

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 259738 Type: WELL API Number: 009-06617 Status: SI Insp. Status: SI

Producing Well

Comment: Well is SI at time of inspection. Meter shed has been removed and is not capable of production. Form 6A (403383668) has been Approved with a plug date of 12/31/27

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715201176	location photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6779309