



FORM
INSP

Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
11/08/2024

Submitted Date:
11/08/2024

Document Number:
697010384

FIELD INSPECTION FORM

Loc ID
329899

Inspector Name:
Peterson, Tom

On-Site Inspection ☐

2A Doc Num: _____

Operator Information:

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

☐ THIS IS A FOLLOW UP INSPECTION

☐ FOLLOW UP INSPECTION REQUIRED

☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
483367	WELL	DG	04/05/2024		123-51899	CAMENISCH 33-6HZ	SI
483368	WELL	DG	04/06/2024		123-51900	CAMENISCH 33-7HZ	SI
483369	WELL	WO	05/01/2024		123-51901	CAMENISCH 33-2HZ	SI
483370	WELL	DG	04/02/2024		123-51902	CAMENISCH 33-3HZ	SI
483372	WELL	DG	04/04/2024		123-51904	CAMENISCH 33-5HZ	SI
483374	WELL	DG	04/03/2024		123-51906	CAMENISCH 33-4HZ	SI

General Comment:

This is a routine audit. Any corrective actions from previous audits that have not been addressed are still applicable. The production facility is currently under construction.

Date Run: 11/8/2024 Doc [#697010384]

Page 1 of 4

Location				
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	OTHER			
Comment:	Lease road entrance			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	x 6			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Bradenhead	# 6			corrective date
Comment:	Bradenhead valves are exposed at surface.			
Corrective Action:				Date:
Type: Flow Line	# 6			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 6			
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 483367 Type: WELL API Number: 123-51899 Status: DG Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 483368 Type: WELL API Number: 123-51900 Status: DG Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 483369 Type: WELL API Number: 123-51901 Status: WO Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 483370 Type: WELL API Number: 123-51902 Status: DG Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 483372 Type: WELL API Number: 123-51904 Status: DG Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 483374 Type: WELL API Number: 123-51906 Status: DG Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697010385	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6779301