

Inspection Photos
Location: QB ENERGY Mesa/F26-697
Location ID: 448472
Date: 11/04/2024



Nov 4, 2024 at 2:33:41 PM
+39.495485, -108.190617 ±4.74m
Parachute



Nov 4, 2024 at 3:52:28 PM
+39.502214, -108.186000 ±4.71m
Parachute

Photo # 8587 Entrance to location

Photo # 8664 Location sign from lease road

Inspection Photos

Location: QB ENERGY Mesa/F26-697

Location ID: 448472

Date: 11/04/2024



Photo # 8589 Location



Photo # 8592 Location



Inspection Photos
Location: QB ENERGY Mesa/F26-697
Location ID: 448472
Date: 11/04/2024



Photo # 8596 Location



Photo # 8604 Location



Inspection Photos
Location: QB ENERGY Mesa/F26-697
Location ID: 448472
Date: 11/04/2024



Photo # 8608 Location



Photo # 8610 No tank battery sign

Inspection Photos
Location: QB ENERGY Mesa/F26-697
Location ID: 448472
Date: 11/04/2024



Photo # 8633 Location



Photo # 8646 SE corner of location

Inspection Photos
Location: QB ENERGY Mesa/F26-697
Location ID: 448472
Date: 11/04/2024




Photo # 8647 NE corner of location




Photo # 8648 NW corner of location

Inspection Photos
Location: QB ENERGY Mesa/F26-697
Location ID: 448472
Date: 11/04/2024



Photo # 8649 SW corner of location



**Photo # 8603 PRV vent line does not comply with CECMC
pressure safety device rules**

Inspection Photos

Location: QB ENERGY Mesa/F26-697

Location ID: 448472

Date: 11/04/2024



Photo # 8614 Tank labels damaged and illegible



Photo # 8618 Tank labels damaged and illegible



Inspection Photos
Location: QB ENERGY Mesa/F26-697
Location ID: 448472
Date: 11/04/2024



Photo # 8620 Tank labels damaged and illegible



Photo # 8635 Unused equipment on location