

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2024

Submitted Date:

11/02/2024

Document Number:

708904948**FIELD INSPECTION FORM**Loc ID 322404 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10770Name of Operator: VISION ENERGY LLCAddress: P O BOX 370City: IGNACIO State: CO Zip: 81137**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**24 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Vision		pbechtolt@maralexinc.com	
, Vision		mrinc20@maralexinc.com	
, Vision		mollieo@maralexinc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210419	WELL	TA	11/01/2020	GW	045-06175	BALDY CREEK UNIT 1-17	TA

General Comment:**CECMC Inspection Report Summary**

On 10/24/2024 at approximately 12:21 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at VISION ENERGY LLC BALDY CREEK UNIT 1-17 Pad Location # 322404 in Garfield County Colorado.
Location is within High Priority/Density/NSO/Black Bear Habitat areas.
Location is approximately 30 yards from Baldy Creek.
While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Signs/Marker - Tank label on production tank contains inaccurate info/does not comply with CECMC rules with a CA date of 12/02/2024
2. Housekeeping - Open ended piping/available for entry by wildlife/wildlife hazard with a CA date of 11/09/2024
3. Equipment - Meter calibration info not conspicuously posted with a CA date of 12/02/2024
4. Equipment - Open ended load line with a CA date of 11/09/2024
5. Tanks & Berms - Secondary containment is insufficient/does not comply with CECMC secondary containment rules with a CA date of 11/22/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank label on production tank contains inaccurate info/does not comply with CECMC rules		
Corrective Action:	Comply with CECMC tank labeling rules	Date:	12/02/2024
Emergency Contact Number:			
Comment:	970-563-0082		
Corrective Action:			
		Date:	
Good Housekeeping:			
Type	OTHER		
Comment:	Open ended piping/available for entry by wildlife/wildlife hazard		
Corrective Action:	Comply with CECMC wildlife rules		Date: 11/09/2024
Type	WEEDS		
Comment:	Weeds encroaching on equipment in multiple areas		
Corrective Action:			
		Date:	
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		

Comment:	Pipe rail fence around heater on production tank		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Pipe rail fence		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Fencing		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Gas Meter Run	# 1		
Comment:	Meter calibration info not conspicuously posted		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.	Date:	12/02/2024
Type: Gas Meter Run	# 1		
Comment:	Summit Midstream		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Open ended load line		
Corrective Action:	All load lines will be capped or plugged	Date:	11/09/2024
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	400 BBLS	HEATED STEEL AST		,	
Comment:	Tank not equipped with telemetry					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment:	<p>Secondary containment is insufficient/does not comply with CECMC secondary containment rules.</p> <p>Additionally secondary containment is overrun with vegetation & compromised.</p>				
Corrective Action:	Comply with CECMC secondary containment rules			Date:	11/22/2024

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	210419	Type:	WELL	API Number:	045-06175	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: Shut In Last produced September 2009 Last MIT 06/13/2023 - document # 403444969									
Corrective Action: _____ Date: _____									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse to none in areas
Compaction						Small amount of light compaction
Other						Cut slope showing signs of lack of stabilization
		Culverts				
		Compaction				Light compaction in some areas
Ditches						
Culverts						
		Gravel				Sparse to none in areas
		Ditches				

Comment: [Cut slope showing some signs of lack of stabilization](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
Please refer to Signs/Marker, Housekeeping, Equipment & Tanks & Berms for corrective actions.	smelserw	11/02/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403980100	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6770905
708904949	Inspection 708904948 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6770902
708904950	Inspection 708904948 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6770903