

Inspection Photos  
Location: QB ENERGY Mesa/N23-697  
Location ID: 448427  
Date: 11/04/2024



Photo # 8667 Entrance to location




Photo # 8712 Location

**Inspection Photos**  
**Location: QB ENERGY Mesa/N23-697**  
**Location ID: 448427**  
**Date: 11/04/2024**



**Photo # 8669 Location**



**Photo # 8673 Location**



**Inspection Photos**  
**Location: QB ENERGY Mesa/N23-697**  
**Location ID: 448427**  
**Date: 11/04/2024**



**Photo # 8676 Location**



**Photo # 8707 Location**

**Inspection Photos**  
**Location: QB ENERGY Mesa/N23-697**  
**Location ID: 448427**  
**Date: 11/04/2024**



**Photo # 8710 Location**



**Photo # 8711 Location**



**Inspection Photos**  
**Location: QB ENERGY Mesa/N23-697**  
**Location ID: 448427**  
**Date: 11/04/2024**



**Photo # 8741 NE corner of location**



**Photo # 8782 NW corner of location**

**Inspection Photos**  
**Location: QB ENERGY Mesa/N23-697**  
**Location ID: 448427**  
**Date: 11/04/2024**



**Photo # 8745 SW corner of location**



**Photo # 8746 SE corner of location**



**Inspection Photos**  
**Location: QB ENERGY Mesa/N23-697**  
**Location ID: 448427**  
**Date: 11/04/2024**



**Photo # 8680 Rupture disc vent lines do not comply with CECMC pressure safety**



**Photo # 8688 PRV vent line does not comply with CECMC pressure safety device rules**

Inspection Photos  
Location: QB ENERGY Mesa/N23-697  
Location ID: 448427  
Date: 11/04/2024



Photo # 8691 PRV & Rupture disc vent line do not comply with CECMC pressure safety device rules



Photo # 8693 PRV vent line does not comply with CECMC pressure safety device rules



Inspection Photos  
Location: QB ENERGY Mesa/N23-697  
Location ID: 448427  
Date: 11/04/2024



Photo # 8695 PRV vent line does not comply with CECMC pressure safety device rules




Photo # 8697 PRV vent line does not comply with CECMC pressure safety device rules

**Inspection Photos**  
**Location: QB ENERGY Mesa/N23-697**  
**Location ID: 448427**  
**Date: 11/04/2024**



**Photo # 8699 PRV vent line does not comply with CECMC pressure safety device rules**



**Photo # 8701 PRV vent line does not comply with CECMC pressure safety device rules**



## Inspection Photos

Location: QB ENERGY Mesa/N23-697

Location ID: 448427

Date: 11/04/2024



Photo # 8703 PRV vent line does not comply with CECMC pressure safety device rules




Photo # 8714 Tank labels damaged and illegible

Inspection Photos  
Location: QB ENERGY Mesa/N23-697  
Location ID: 448427  
Date: 11/04/2024



Photo # 8715 Tank labels damaged and illegible




Photo # 8716 Tank labels damaged and illegible



## Inspection Photos

Location: QB ENERGY Mesa/N23-697

Location ID: 448427

Date: 11/04/2024




Photo # 8717 Tank labels damaged and illegible



Photo # 8723 Tank labels damaged and illegible



Inspection Photos  
Location: QB ENERGY Mesa/N23-697  
Location ID: 448427  
Date: 11/04/2024




Photo # 8724 Tank labels damaged and illegible



Photo # 8728 Unused equipment on location



**Inspection Photos**  
**Location: QB ENERGY Mesa/N23-697**  
**Location ID: 448427**  
**Date: 11/04/2024**



**Photo # 8729 Unused equipment on location**



**Photo # 8738 Some labels are peeling and becoming illegible**

**Inspection Photos**  
**Location: QB ENERGY Mesa/N23-697**  
**Location ID: 448427**  
**Date: 11/04/2024**



**Photo # 8739 Debris**