

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HONEA 19-05 Pad

Location # 335038



Photo # 8884 From entrance to location



Photo # 8885 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HONEA 19-05 Pad

Location # 335038



Photo # 8886 Location

Photo # 8887 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HONEA 19-05 Pad

Location # 335038



Photo # 8888 Location



Photo # 8889 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HONEA 19-05 Pad

Location # 335038



Photo # 8890 Location



Photo # 8891 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HONEA 19-05 Pad

Location # 335038



Photo # 8892 Location

Photo # 8893 Location

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC HONEA 19-05 Pad

Location # 335038



Nov 4, 2024 at 2:17:31 PM

Photo # 8894 Location



Nov 4, 2024 at 2:17:57 PM

Photo # 8895 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HONEA 19-05 Pad

Location # 335038



Photo # 8896 Location



Photo # 8897 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HONEA 19-05 Pad

Location # 335038



Photo # 8898 Location



Photo # 8899 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HONEA 19-05 Pad

Location # 335038



Photo # 8900 Methanol tank missing some required info /does not comply with CECMC labeling rules



Photo # 8901 Methanol tank missing some required info /does not comply with CECMC labeling rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HONEA 19-05 Pad

Location # 335038



Photo # 8902 Tank label damaged & peeling/some required info is illegible




Photo # 8903 Tank label peeling/some required info is starting to become illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HONEA 19-05 Pad

Location # 335038



Photo # 8904 Rupture disc vent line does not comply with CECMC pressure safety device rules



Photo # 8905 Rupture disc vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HONEA 19-05 Pad

Location # 335038




Photo # 8906 PRV vent lines do not comply with CECMC pressure safety device rules



Photo # 8907 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HONEA 19-05 Pad

Location # 335038



Photo # 8908 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 8909 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HONEA 19-05 Pad

Location # 335038



Photo # 8910 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 8911 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HONEA 19-05 Pad

Location # 335038



Photo # 8912 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 8913 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HONEA 19-05 Pad

Location # 335038



Photo # 8914 Natural gas generator & air compressor not listed in operators FORM 2A or in any FORM 4 SUNDRY /operator is not in compliance with CECMC rules



Photo # 8915 Total of seven 500 bbl tanks in battery on location – FORM 2A submitted by operator only lists 6 tanks/operator is out of compliance