

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



Photo # 8500 From entrance to location



Photo # 8501 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015




Photo # 8502 Location



Photo # 8503 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



Oct 30, 2024 at 1:37:46 PM
CO

Photo # 8504 Location



Oct 30, 2024 at 1:39:40 PM
CO

Photo # 8505 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



Photo # 8506 Location



Photo # 8507 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



Photo # 8508 Unmarked deadman



Photo # 8509 Same unmarked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



Photo # 8510 Unused equipment



Photo # 8511 Unused equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



Photo # 8512 PRV vent line does not comply with CECCM pressure safety device rules



Photo # 8513 PRV vent line does not comply with CECCM pressure safety device rules