

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/28/2024

Submitted Date:

11/04/2024

Document Number:

708904970**FIELD INSPECTION FORM**Loc ID 335638 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**42 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283572	WELL	PR	08/01/2023	GW	045-11943	FEDERAL RWF 331-11	PR
289766	WELL	PR	03/22/2007	GW	045-13866	FEDERAL RWF 532-11	PR
289768	WELL	PR	03/22/2007	GW	045-13864	FEDERAL RWF 31-11	PR
289769	WELL	PR	10/01/2022	GW	045-13863	FEDERAL RWF 41-11	PR
289770	WELL	PR	11/30/2007	GW	045-13862	FEDERAL RWF 441-11	PR
289771	WELL	PR	08/01/2020	GW	045-13861	FEDERAL RWF 341-11	PR
289772	WELL	PR	08/01/2020	GW	045-13860	FEDERAL RWF 542-11	PR
289774	WELL	PR	03/22/2007	GW	045-13858	FEDERAL RWF 442-11	PR
289939	WELL	PR	07/01/2022	GW	045-13924	FEDERAL RWF 541-11	PR

**General Comment:****CECMC Inspection Report Summary**

On 10/28/2024 at approximately 11:55 hours, I, Compliance Specialist, Wayne Smelser  
 Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC FEDERAL RWF 331-11 Pad.  
 Location # 335638 in Garfield County Colorado.  
 Location is within High Priority/Density/Black Bear Habitat areas.  
 While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Stormwater - Failure to minimize erosion & transport of sediment/BMP's need maintenance, sediment trap needs maintenance & erosion & transport of sediment onto lease road/insufficient BMP's with a CA date of 11/19/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911/970-285-9377		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	OTHER		
Comment:	Small amount of staining near some wellheads		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Liquid nitrogen tank & catalytic heater - hog panels		

Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical tanks - hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 12		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 12		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 5		
Comment:	<p>4 marked &amp; 1 unmarked deadman - please refer to photo log</p> <p>All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.</p>		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Catalytic heater		
Corrective Action:		Date:	
Type: Bradenhead	# 9		
Comment:	Taylor plugs located on all bradenhead, bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Liquid nitrogen tank		
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	

Type: Bird Protectors	# 6	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		,
Comment:	Tanks equipped with telemetry				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:	Centralized containment			
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities				
Facility ID:	283572	Type:	WELL	API Number: 045-11943 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	289766	Type:	WELL	API Number: 045-13866 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	289768	Type:	WELL	API Number: 045-13864 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	289769	Type:	WELL	API Number: 045-13863 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	289770	Type:	WELL	API Number: 045-13862 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	289771	Type:	WELL	API Number: 045-13861 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	289772	Type:	WELL	API Number: 045-13860 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	289774	Type:	WELL	API Number: 045-13858 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	289939	Type:	WELL	API Number:	045-13924	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

--	--	--	--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Waddles	Fail					BMP's need maintenance
		Other				Hay bales
		Gravel				Sparse to none in sections
Berms						
		Compaction				Small amount of light compaction
Other	Fail					Failure to minimize erosion & sediment transport
		Other	Fail			Erosion & transport of sediment onto lease road
		Culverts				
Rip Rap						
Sediment Traps	Fail					BMP needs maintenance
Compaction						Small amount of light compaction
Check Dams						
Gravel						Sparse to none in most areas
		Berms	Fail			BMP's need maintenance
				Material Handling And Spill Prevention		Chemical tank containments
		Ditches				

Comment: 1. Failure to minimize erosion & transport of sediment/BMP's need maintenance  
 2. Sediment trap needs maintenance  
 3. Erosion & transport of sediment onto lease road/insufficient BMP's  
 4. Tunnel erosion & transport of sediment onto lease road/BMP's need maintenance  
 Large amount of sediment buildup at hay bales/BMP's may need maintenance in near future

Corrective Action: **Comply with CECMC Stormwater rules**

Date: 11/19/2024

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
Please refer to Stormwater for corrective actions & also refer to Housekeeping & Equipment for comments.	smelserw	11/04/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:



Document Num	Description	URL
403982108	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6773370">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6773370</a>
708904971	Inspection 708904970 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6773368">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6773368</a>
708904972	Inspection 708904970 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6773369">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6773369</a>