

FORM  
INSPRev  
X/20

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/01/2024

Submitted Date:

11/04/2024

Document Number:

717000123

### FIELD INSPECTION FORM

Loc ID 320072 Inspector Name: Finkenbinder, Chane On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 74165  
Name of Operator: RENEGADE OIL & GAS COMPANY LLC  
Address: 6155 S MAIN STREET #225  
City: AURORA State: CO Zip: 80016

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 10 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	<a href="#">All Inspections</a>
Espinosa, Bill		billespinosa30@yahoo.com	<a href="#">Inspections</a>
Condill, J.B.	(303) 680-4725	jbcrog@aol.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202512	WELL	SI	12/01/2018	OW	001-07917	CHAMPLIN 67 AMOCO L 1	SI

**General Comment:**

[Routine Inspection](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment: Adequate

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Rule 606: Weeds, dead weeds.		
Corrective Action:	Remove weeds, dead weeds. Within the designated setback (25 feet around any and all equipment), debris and weeds per Rule 606. Corrective Action Date 11/22/2024. See attached photos # 3 & 4.	Date:	11/22/2024
Type	UNUSED EQUIPMENT		
Comment:	Rule 606: unnecessary / unused equipment		
Corrective Action:	Remove all unnecessary / unused equipment. Within the designated setback (25 feet around any and all equipment). Corrective Action Date 12/6/2024 for unused equipment. See attached photos # 3 & 4.	Date:	12/06/2024

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Equipment:**

Type	#		corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.902668,-104.432449

Comment:		
Corrective Action:		Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Wells Served By Facilities Above**

**AirsID**

API Number	API Number	AirsID
001-07917		

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 202512 Type: WELL API Number: 001-07917 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 06/27/2023 Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Appeared to be plumbed to the surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection Report Summary                      On Friday November 1st at approximately 14:00pm. I, Inspector Chane Finkenbinder, conducted an on-site inspection.                      Operator: RENEGADE OIL &amp; GAS COMPANY                      Location name: CHAMPLIN 67 AMOCO L #1                      API # 05-001-07917                      Location ID #: 320072                      County: Adams                      While there, I observed a shut in well.                      During this inspection the following possible compliance issues were observed:                      Rule 606: Weeds, dead weeds &amp; unnecessary / unused equipment. Within the designated setback (25 feet around any and all equipment), debris and weeds per Rule 606. Corrective Action Date 11/22/2024 for the weeds &amp; 12/6/2024 for unused equipment. See attached photos # 3 &amp; 4.                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	finkenbc	11/04/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403981738	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6772929">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6772929</a>
717000124	Inspection photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6772925">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6772925</a>