

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SOUTH LEVERICH 13-09 Pad

Location #: 335045



Photo # 8975 From entrance to location

Photo # 8976 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SOUTH LEVERICH 13-09 Pad

Location #: 335045



Photo # 8977 Location



Photo # 8978 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SOUTH LEVERICH 13-09 Pad

Location #: 335045



Photo # 8979 Location

Photo # 8980 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SOUTH LEVERICH 13-09 Pad

Location #: 335045



Photo # 8981 Location



Photo # 8982 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SOUTH LEVERICH 13-09 Pad

Location #: 335045



Photo # 8983 Location

Photo # 8984 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SOUTH LEVERICH 13-09 Pad

Location #: 335045



Photo # 8985 Location



Photo # 8986 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SOUTH LEVERICH 13-09 Pad

Location #: 335045



Photo # 8987 Location



Photo # 8988 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SOUTH LEVERICH 13-09 Pad

Location #: 335045



Photo # 8989 Rupture disc vent line does not comply with CECMC pressure safety device rules



Photo # 8990 Rupture disc vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SOUTH LEVERICH 13-09 Pad

Location #: 335045



Photo # 8991 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 8992 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SOUTH LEVERICH 13-09 Pad

Location #: 335045




Photo # 8993 Rupture disc vent line does not comply with CECMC pressure safety device rules




Photo # 8994 Rupture disc vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SOUTH LEVERICH 13-09 Pad

Location #: 335045



Photo # 8995 Wellhead sign laying on ground/not properly posted

Photo # 8996 Tank battery contains seven 500 bbl tanks
FORM 2A submitted by operator only lists 6 tanks/operator
is not in compliance with CECMC rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SOUTH LEVERICH 13-09 Pad

Location #: 335045



Photo # 8997 Pig station not listed is operators FORM 2A & Buy Back Meter listed in FORM 2A as Temporary Equipment/ operator is not in compliance with CECMC rules



Photo # 8998 Two Chemical tanks not listed in FORM 2A/not in compliance with CECMC rules