

Operator: *BONANZA CREEK ENERGY OPERATING CO.*

Location Name: PRONGHORN-65N61W 17NWNW

Loc ID: 305141

Inspection: 708201748



Exhibit A



Exhibit B

CA: This location does not comply with Rule 1004. During this inspection, it was observed that the access road does not appear to have been recontoured/graded to reflect the adjacent topography. Additionally, the former well location has evidence of bare/exposed soils and road base debris. Other portions of the reclaimed areas appear to be progressing towards reclamation standards with desirable vegetation observed. Refer to attached inspection photos. Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

CA Resolution: Operator has addressed the CA issue, property has been contoured to match existing grade and re-seeded. as well in order to comply with Rule 606.