

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/12/2024

Submitted Date:

11/13/2024

Document Number:

718000008**FIELD INSPECTION FORM**Loc ID 417178 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10671Name of Operator: EDGE ENERGY II LLCAddress: 600 12TH STREET SUITE 115City: GOLDEN State: CO Zip: 80401**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Turner, Ben		bturner@edgeenergy1.com	Edge Energy
Kelsi Welch		Kelsi.welch@iptwell.com	IPT

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417182	WELL	TA	04/01/2024	OW	123-31598	STATE 36-10-67 1H	EI

General Comment:

ECMC Environmental Inspection of Remediation Project 35376, Spill ID 488467.

All facilities appear to have been removed from the location. An open excavation is present in the area of the former ASTs.

Operator has not provided sample results from heater treater/separator, flowline risers or the well and pumpjack area. Operator is directed to proceed in accordance with conditions of approval for Remediation Project 35376, and Form 27 Document #s 403768245 and 403947986.

Inspected Facilities									
Facility ID:	417182	Type:	WELL	API Number:	123-31598	Status:	TA	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental

Spill/Remediation:

Comment:

ECMC Environmental Inspection of Remediation Project 35376, Spill ID 488467.

All facilities appear to have been removed from the location. An open excavation is present in the area of the former ASTs.

Operator has not provided sample results from heater treater/separator, flowline risers or the well and pumpjack area. Operator is directed to proceed in accordance with conditions of approval for Remediation Project 35376, and Form 27 Document #s 403768245 and 403947986.

Corrective Action:

Submit Supplemental Form 27 on a quaterly basis until project is resolved. Next Form 27 is due 01/7/2025

Date: 01/07/2025

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
718000009	State36-10-67-1HPhotos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6785527