

Inspection Photos

November 5th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333907

Inspection Document #: 714001455

La Plata County, CO

Township: SWNE 2 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Barnes Leidy 2, 4
Location ID: 333907

11/5/24
49° NE



Photo 1. View of well disturbance taken from the access point facing center.

Inspection Photos
Location Name: Barnes Leidy 2, 4
Location ID: 333907



Photo 2. View of erosion forming along existing stormwater BMPs in the southern portion of the pad. Round river rock is likely contributing to formation of erosion.

Inspection Photos
Location Name: Barnes Leidy 2, 4
Location ID: 333907

11/5/24
325° NW



Inspection Photos
Location Name: Barnes Leidy 2, 4
Location ID: 333907



Photo 4. View of perimeter stormwater BMPs/wattles that are not installed correctly and no longer functioning. Determine if stormwater BMPs are needed if not wattles are considered debris and need to be removed.

Inspection Photos
Location Name: Barnes Leidy 2, 4
Location ID: 333907



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of reference area composed of Sagebrush, Juniper, Broom Snakeweed and Indian Ricegrass.

API #: 067-08769, 09613