

# Inspection Photos

November 5th, 2024

Operator: Simcoe LLC - 10749

Location ID: 312051

Inspection Document #: 714001456

La Plata County, CO

Township: SESW 2 33N 9W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos  
Location Name: Barnes A2  
Location ID: 312051

11/5/24  
271° W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 1.** View of well disturbance taken from the access point facing center.

API #: 067-08731



Inspection Photos  
Location Name: Barnes A2  
Location ID: 312051



**Photo 2.** View of small Musk Thistle infestation observed in the eastern and southern portions of the disturbance.



Inspection Photos  
Location Name: Barnes A2  
Location ID: 312051



**Photo 3.** Musk Thistle observed in the western interim reclamation area.



Inspection Photos  
Location Name: Barnes A2  
Location ID: 312051



**Photo 4.** View of stormwater BMP wattles that are filled in with sediment and no longer functioning.



Inspection Photos  
Location Name: Barnes A2  
Location ID: 312051



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** View of large patch of Houndstongue observed in the western portion of the disturbance.

API #: 067-08731



Inspection Photos  
Location Name: Barnes A2  
Location ID: 312051

11/5/24  
296° NW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 6.** View of pasture reference area composed predominantly of Smooth Brome and Squirrel Tail.

API #: 067-08731