

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/12/2024

Submitted Date:

11/13/2024

Document Number:

708303060**FIELD INSPECTION FORM**Loc ID 335766 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**ECMC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, CAERUS		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259576	WELL	PR	03/01/2019	GW	045-07754	CHEVRON 43-5D	PR
259577	WELL	PR	03/01/2019	GW	045-07755	CHEVRON 44-5D	PR

General Comment:**CECMC Inspection Report Summary**

On 11/12/2024 at approximately 11:00, Compliance Inspector Matthew Morris conducted a follow-up inspection at CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWW at Location ID #335766 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

1) Multiple wildlife entry hazards

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970)285-2615

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Multiple wildlife entry hazards on separators and heating insulation at tank battery.		
Corrective Action:	Secure equipment to prevent wildlife entry.	Date:	11/18/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Barbed wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe rails		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	Liquid nitrogen tanks. One tank possibly leaking.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 6		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:	Date:			

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: 259576	Type: WELL	API Number: 045-07754	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 259577	Type: WELL	API Number: 045-07755	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Sediment Traps				
		Ditches				
		Gravel				
Gravel						
		Rip Rap				
		Culverts				
Berms						
Compaction						
		Check Dams				
		Compaction				

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708303061	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6785978