

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/29/2024

Submitted Date:

11/07/2024

Document Number:

709100440**FIELD INSPECTION FORM**Loc ID: 312292 Inspector Name: Heibel, Krystal On-Site Inspection: ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 95620Name of Operator: WESTERN OPERATING COMPANYAddress: 1165 DELAWARE STREET #200City: DENVER State: CO Zip: 80204**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments3 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kyle Waggoner		kyle.waggoner@state.co.us	
James, Steven	(303) 893-2438	steve@westernoperating.com	<a href="#">All Inspections</a>
Krystal Heibel		krystal.heibel@state.co.us	
Dylan Edwardson		dylan.edwardson@state.co.us	
Alex Fischer		alex.fischer@state.co.us	
Ryan Finley		rfinley@entradainc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221086	WELL	SI	05/01/2024	OW	075-09212	PROPST 2	EI
312292	LOCATION	AC	05/09/2024		-	PROPST-611N53W 27NESE	EI

**General Comment:**

On October 29, 2024, ECMC Environmental Staff Krystal Heibel, Dylan Edwardson, Alex Fischer and Kyle Waggoner conducted an environmental field inspection of Western Operating Company (Western) Probst B #2 (Location ID: 312292).

During the time of the inspection, Ryan Finley (Entrada), Nick Yourd (Entrada), Ted Propst (surface owner), and Todd Troutman (DC Dozer Service) were on location.

This location has an associated AOC with Order No. (1V-870). Weather was cloudy and windy. For the most recent field inspection report of this facility, please refer to Document #709100421.

The following is a summary: Pit Facility ID 100311 is not in use and the Propst 2 well (API 075-09212) was active. The pit's berms were pushed into a stockpile south of the location and excavation to the west of the pit resulted in an additional stockpile on location. It appears that the excavation has increased the footprint of the oil and gas facility's location.

Refer to the photo-documentation of the observed compliance issues attached to this report. Any corrective action(s) and corrective action due dates from previous inspections that have not been addressed are still applicable.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type			
Comment:	Additional stockpile observed on location with proper signage		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Emergency contact number visible from a distance.		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	During the December 20, 2023 (Doc #709100195), January 24, 2024 (Doc# 709100206), and March 20, 2024 (Doc# 709100246) inspections, an approx. 3600 cubic-yard stockpile has been added to the south of the location and a 2700 cubic-yard stockpile has also been added to the west of the location, which increased the footprint by approx. 2.25 acres.		
Corrective Action:	Operator shall submit an updated Form 2A (Oil and Gas Location Assessment) to the ECMC to increase the existing Oil and Gas Location, as required by Rule 304.		Date: 01/29/2024
Type	TRASH		
Comment:	Trash and debris throughout the location.		
Corrective Action:	Comply with Rule 606		Date: 07/13/2024

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: At the time of inspection, hydrocarbon soil staining observed within the excavation area of the tank battery. Todd Troutman was actively excavating the area during inspection.

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type			
Comment:	It appears that the excavation is properly fenced off to exclude wildlife, livestock and/or personnel.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type:	#		
Comment:	A 3" valve near the wellhead was not plugged.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e		Date: 08/24/2023

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	221086	Type:	WELL	API Number:	075-09212	Status:	SI	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	312292	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		Refer to FIR, Doc# 708201763 for additional Interim Reclamation and Stormwater Inspection information.				
Corrective Action:						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403987023	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6778084">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6778084</a>
709100444	Pictures	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6778068">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6778068</a>
709100445	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6778069">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6778069</a>