

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403994875

Date Received:
11/14/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Engineering

dnr_cogccengineering@state.co.us

Toews, Wesley

wtoews@blm.gov

TEP

COGCCInspectionReports@terraep.com

Haverkamp, Curtis

curtis.haverkamp@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 708904921

Inspection Date: 10/30/2024

FIR Submit Date: 10/30/2024

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335176

Location Name: FEDERAL-66S94W Number: 19NESE County: _____

Qtrqtr: NESE Sec: 19 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.509096 Longitude: -107.924075

FACILITY - API Number: 05-045- -00 Facility ID: 335176

Facility Name: FEDERAL-66S94W Number: 19NESE

Qtrqtr: NESE Sec: 19 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.509096 Longitude: -107.924075

CORRECTIVE ACTIONS:

1 CA# 200173

Corrective Action: All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition.

Date: 10/31/2024

Response: CA COMPLETED

Date of Completion: 10/31/2024

Storm water from well head was evacuated on 10/31/24. Vac-truck conducted hydro-excavation around well

Operator Comment: head. Very small leak on Larkin head fitting was discovered and was welded / repaired the same day. Repair job on Larkin head was tested and found to be successful. Excavation was backfilled, Corrective action complete.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Storm water from well head was evacuated on 10/31/24. Vac-truck conducted hydro-excavation around well head. Very small leak on Larkin head fitting was discovered and was welded / repaired the same day. Repair job on Larkin head was tested and found to be successful. Excavation was backfilled, Corrective action #200173 complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental Lead

Date: 11/14/2024 11:57:35 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403994875	FIR RESOLUTION SUBMITTED
403994912	Source of well head leak at RMV 63-19. Repaired on 10/31/24.

Total Attach: 2 Files