

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2024

Submitted Date:

11/14/2024

Document Number:

714201867**FIELD INSPECTION FORM**Loc ID 442961 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442954	WELL	PR	07/04/2016	OW	123-42068	SUNFLOWER 40C-17HZ	PR
442955	WELL	PR	07/01/2022	OW	123-42069	SUNFLOWER 7N-17HZ	PR
442956	WELL	PR	09/01/2018	OW	123-42070	SUNFLOWER 8N-17HZ	PR
442957	WELL	PR	09/01/2018	OW	123-42071	SUNFLOWER 7C-17HZ	PR
442958	WELL	PR	09/01/2018	OW	123-42072	SUNFLOWER 25G-17HZ	PR
442959	WELL	PR	09/01/2018	OW	123-42073	SUNFLOWER 24N-17HZ	PR
442960	WELL	PR	09/01/2018	OW	123-42074	SUNFLOWER 40N-17HZ	PR

**General Comment:**

This is an audit of SUNFLOWER 25G-17HZ, 7N-17HZ, 7C-17HZ, 24N-17HZ, 8N-17HZ, 40C-17HZ, 40N-17HZ scout card and related documents followed by a field inspection.

Location				
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Adequate			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	panel			
Corrective Action:				Date:
Equipment:				
Type: Plunger Lift	# 7			corrective date
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 7			
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities			
Facility ID: 442954	Type: WELL	API Number: 123-42068	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: PR; valves appear to be in the open position.			
Corrective Action:		Date:	
<b>BradenHead</b>			
Date of Last Brhd Test: 11/15/2023		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 46      Fluid Type: GAS	
End Surf Csg Pressure: 1			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 442955	Type: WELL	API Number: 123-42069	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: PR; valves appear to be in the open position.			
Corrective Action:		Date:	
<b>BradenHead</b>			
Date of Last Brhd Test: 06/12/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 6      Fluid Type: NONE	
End Surf Csg Pressure: 0			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 442956	Type: WELL	API Number: 123-42070	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: PR; valves appear to be in the open position.			
Corrective Action:		Date:	
<b>BradenHead</b>			
Date of Last Brhd Test: 04/17/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 16      Fluid Type: None	
End Surf Csg Pressure: --			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 442957	Type: WELL	API Number: 123-42071	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: PR; valves appear to be in the open position.			
Corrective Action:		Date:	

<b>BradenHead</b>			
Date of Last Brhd Test:	11/15/2023	Annual Brhd Completed?	Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 13	Fluid Type:	GAS
	End Surf Csg Pressure: 1		
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	442958	Type:	WELL	API Number:	123-42072	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<b>Producing Well</b>			
Comment:	PR; valves appear to be in the open position.		
Corrective Action:		Date:	

<b>BradenHead</b>			
Date of Last Brhd Test:	04/16/2024	Annual Brhd Completed?	Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 1	Fluid Type:	None
	End Surf Csg Pressure: --		
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	442959	Type:	WELL	API Number:	123-42073	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<b>Producing Well</b>			
Comment:	PR; valves appear to be in the open position.		
Corrective Action:		Date:	

<b>BradenHead</b>			
Date of Last Brhd Test:	04/16/2024	Annual Brhd Completed?	Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 1	Fluid Type:	None
	End Surf Csg Pressure: --		
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	442960	Type:	WELL	API Number:	123-42074	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<b>Producing Well</b>			
Comment:	PR; valves appear to be in the open position.		
Corrective Action:		Date:	

BradenHead			
Date of Last Brhd Test: 04/17/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results	Initial Surf Csg Pressure: 6	Fluid Type: None	
	End Surf Csg Pressure: --		
Comment:	<div></div>		
Corrective Action:	<div></div>	Date: <div></div>	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<a href="#">Routine inspection. Weather conditions: sunny, muddy.</a>	santistb	11/14/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714201868	photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6786998">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6786998</a>