

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/15/2024

Submitted Date:

11/15/2024

Document Number:

707603353

FIELD INSPECTION FORM

Loc ID 302223 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 69175
 Name of Operator: PDC ENERGY INC
 Address: 1099 18TH STREET SUITE 1500
 City: DENVER State: CO Zip: 80202

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287132	WELL	PR	12/01/2019	OW	123-27380	FRANCIS 21-8	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / WORKOVER / CEMENTING** inspection.
 Well(s): 1: Plugged & Abandoned | PA.
 Plugging Operations: Cementing; Cement-surface.
 Battery: Inactive. Shut-down.
 Inactive Battery SE corner GPS coordinates: 40.505344 / -104.583273
 Well GPS coordinates: 40.506560 / -104.577110

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Jobsite entrance & safety signage posted.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type:	Plunger Lift	# 0	corrective date
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:			Date:
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 287132 Type: WELL API Number: 123-27380 Status: PR Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Duco Services Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 6810'-3639'-2797'-0' Cement Volume (sx): 88 sxs

Good Return During Job: _____ Cement Type: Class "G" Neat 15.8#

Comment: 2024/11/15:
 Plugging Operations: Cementing; cement-surface.
 2024/11/15: JSA attached as photo to this report.

Workover Contractor: Ensign Energy Services Rig #356.
 Cement Contractor: Duco Services.

HELD SAFETY MEETING. REVIEW SYLA'S. PERFORM SWC'S AND INSPECTIONS (WSEA 2-A). CHECKED FOR PRESSURE/FLOW (WSEA-10C). HELD SAFETY MEETING WITH RANGER WIRELINE (WSEA-2A). RU WIRELINE. SET CIBP AT 6810'. BAILED 2 SACKS. LOADED HOLE WITH FRESH WATER. PRESSURE TESTED CASING/CIBP TO 1500 PSI (WSEA-10B). SET CIBP AT 3639'. BAILED 2 SACKS. SET CIBP AT 2797'. RD WIRELINE. TIH W/ 86 JOINTS OF 2 3/8 4.7# J-55 8RD EUE TUBING. HELD SAFETY MEETING WITH DUCO CEMENT. RU CEMENT UNIT. PUMPED 5BBLS FRESH WATER. PUMPED 10 SACKS NEAT G. PUMPED 10BBLS DISPLACEMENT. RD CEMENT UNIT. LAID DOWN 64 JOINTS OF 2 3/8 4.7# J-55 8RD EUE TUBING. EOT 699'. RU CEMENT UNIT. PUMPED 74 SACKS NEAT G. LAID DOWN 22 JOINTS OF 2 3/8 4.7# J-55 8RD EUE TUBING. RD FLOOR. ND BOP'S. TOPPED OFF WELL. NU WH. RD CEMENT UNIT. RD SERVICE UNIT. DRAINED HARDLINE AND PUMP. RD HARDLINE. CLEANED LOCATION. LOCKED/TAGGED OUT WELL. SHUT DOWN.

Corrective Action: _____ Date: _____

Workover

Comment: 2024/11/15:
 Plugging Operations: Cementing; cement-surface.
 2024/11/15: JSA attached as photo to this report.

Workover Contractor: Ensign Energy Services Rig #356.
 Cement Contractor: Duco Services.

Reference:
 Form 6N on file. Notice of Intent to Abandon date: 09/11/2024. Approved.
 Form 42 on file. Notice of MIRU. Start Date: 11/13/2024. Approved.
 Form 42 on file. Notice of Plugging Operations. Start Date: 11/13/2024. Approved.

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On FRI 11/15/2024 at approximately 12:22 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: PDC ENERGY INC Location Name: FRANCIS-66N64W/8NENW Location ID: 302223 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Mostly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Plugging Operations: Cementing; Cement-surface. Battery: Inactive. Shut-down. Inactive Battery SE corner GPS coordinates: 40.505344 / -104.583273 Well GPS coordinates: 40.506560 / -104.577110</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	11/15/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603354	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6789052