

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/15/2024

Submitted Date:

11/15/2024

Document Number:

707603355

**FIELD INSPECTION FORM**

Loc ID 332020 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269735	WELL	SI	01/01/2024	OW	123-21723	KREPS TRUST 34-6	WK

**General Comment:**

This is a **PLUGGED & ABANDONED WELL / WORKOVER** inspection.  
Well(s): 1: Workover | WK.  
Plugging Operations: Kill well, flare gas.  
Battery: Inactive. Shut-down.  
Inactive Battery SE corner GPS coordinates: 40.489739 / -104.465512  
Well GPS coordinates: 40.509000 / -104.589780

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Jobsite entrance & safety signage posted.		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type	Ignitor/Combustor		
Comment:	Flaring through portable separator / combustor to kill well.		

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 269735 Type: WELL API Number: 123-21723 Status: SI Insp. Status: WK

**BradenHead**

Date of Last Brhd Test: 04/01/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Workover**

Comment: 2024/11/15:  
Plugging Operations: Kill well, flare gas.  
2024/11/15: JSA attached as photo to this report.  
  
Workover Contractor: Ensign Energy Services Rig #349.  
Cement Contractor: Duco Services.  
  
Reference:  
Form 6N on file. Notice of Intent to Abandon date: 11/06/2024. Approved.  
Form 42 on file. Notice of MIRU. Start Date: 11/15/2024. Approved.  
Form 42 on file. Notice of Plugging Operations. Start Date: 11/15/2024. Approved.

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><a href="#">CECMC Inspection Report Synopsis:</a></p> <p>On FRI 11/15/2024 at approximately 13:30 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: PDC ENERGY INC                      Location Name: KREPS TRUST-66N64W/6SWSE                      Location ID: 332020                      Well Name(s) &amp; API:                      Reference:                      See "Inspected Facilities" section on page 1 of this Field Inspection Report.                      Location County: Weld County, Colorado                      Weather: Mostly Sunny, damp from prior storm.</p> <p>While there, I observed:                      Well(s): 1: Workover   WK.                      Plugging Operations: Kill well, flare gas.                      Battery: Inactive. Shut-down.                      Inactive Battery SE corner GPS coordinates: 40.489739 / -104.465512                      Well GPS coordinates: 40.509000 / -104.589780</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	11/15/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603356	Site photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6789053">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6789053</a>