

Inspection Photos
Location Name: Dorris Ackerson Unit 2
Location ID: 318223



Photo 1 well head and equipment



Photo 2 well head and equipment

Inspection Photos
Location Name: Dorris Ackerson Unit 2
Location ID: 318223



Photo 3 mech cond and stained soil



Photo 4 mech cond and stained soil