

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/15/2024

Submitted Date:

11/15/2024

Document Number:

713301273

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
317690 \_\_\_\_\_ Kester, Michael \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Contact Information:**

| Contact Name | Phone        | Email         | Comment                         |
|--------------|--------------|---------------|---------------------------------|
| , KPK        | 303-825-4822 | cogcc@kpk.com | <a href="#">all inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name         | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 239790      | WELL | PR     | 10/01/2023  | GW         | 123-07578 | DORIS ACKERSON UNIT 1 | PR          |

**General Comment:**

[well site inspection](#)

**Location**

Overall Good:

**Signs/Marker:**

|                    |               |       |  |
|--------------------|---------------|-------|--|
|                    | Type WELLHEAD |       |  |
| Comment:           | good          |       |  |
| Corrective Action: |               | Date: |  |

Emergency Contact Number:

Comment:   
 Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |                                   |       |  |
|--------------------|-----------------------------------|-------|--|
|                    | Type PUMP JACK                    |       |  |
| Comment:           | safety guards                     |       |  |
| Corrective Action: |                                   | Date: |  |
|                    | Type OTHER                        |       |  |
| Comment:           | electric disconnect, metal panels |       |  |
| Corrective Action: |                                   | Date: |  |
|                    | Type WELLHEAD                     |       |  |
| Comment:           | post and wire                     |       |  |
| Corrective Action: |                                   | Date: |  |

**Equipment:**

|                           |                            |       |  |  | corrective date |
|---------------------------|----------------------------|-------|--|--|-----------------|
| Type: Bradenhead          | # 1                        |       |  |  |                 |
| Comment:                  | piped to surface           |       |  |  |                 |
| Corrective Action:        |                            | Date: |  |  |                 |
| Type: Prime Mover         | # 1                        |       |  |  |                 |
| Comment:                  | electric                   |       |  |  |                 |
| Corrective Action:        |                            | Date: |  |  |                 |
| Type: Pump Jack           | # 1                        |       |  |  |                 |
| Comment:                  |                            |       |  |  |                 |
| Corrective Action:        |                            | Date: |  |  |                 |
| Type: Ancillary equipment | # 3                        |       |  |  |                 |
| Comment:                  | electric/automation panels |       |  |  |                 |
| Corrective Action:        |                            | Date: |  |  |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 239790 Type: WELL API Number: 123-07578 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Valves appeared to be closed at time of inspection

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 03/13/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

| Comment   | User    | Date       |
|---|---------|------------|
| <u>Audit of scout card and related documents</u><br><u>Routine inspection</u> | kestern | 11/15/2024 |
| <u>This inspection does not nullify any orders or NOAV from the ECMC</u>      |         |            |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 713301274    | site pic    | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6789695">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6789695</a> |