

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2024

Submitted Date:

11/17/2024

Document Number:

693807901

## FIELD INSPECTION FORM

Loc ID 314641 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: 

## Operator Information:

ECMC Operator Number: 10779

Name of Operator: SCOUT ENERGY MANAGEMENT LLC

Address: 13800 MONTFORT DRIVE SUITE 100

City: DALLAS State: TX Zip: 75240

## Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

## Findings:

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response RequestedANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE

## Contact Information:

Contact Name	Phone	Email	Comment
Saint, John		jsaint@scoutep.com	Regional Manager
Devine, Ellice		ellice.devine@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Sanford, Anita	970-640-3572	anita.sanford@scoutep.com	Regulatory Specialist

## Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229176	WELL	SI	04/13/2020	ERIW	103-06261	UNION PACIFIC 26-31	AC

## General Comment:

UIC-5 yr MIT

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	
Type	Main		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	970-675-3700		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	WAG skid		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities

Facility ID: 229176

Type: WELL

API Number: 103-06261

Status: SI

Insp. Status: AC

Underground Injection Control

UIC Violation:

Maximum Injection Pressure:

UIC Routine

Inj./Tube:

Pressure or inches of Hg

Previous Test Pressure

MPP

(e.g. 30 psig or -30" Hg)

Inj Zone: WEBR

TC:

Pressure or inches of Hg

Previous Test Pressure

Last MIT: 04/16/2020

Brhd:

Pressure or inches of Hg

Previous Test Pressure

AnnMTReq:

Comment:

Corrective Action:

Date:

Method of Injection:

Test Type: 5 Year

Tbg psi: 2100

Csg psi: 1310

BH psi: 250

Insp. Status: Pass

Comment:

UIC-5 yr MIT.  
Form 42 Doc#403990495 received 11/12/2024, with test scheduled for 11/22/2024.  
Test date moved to 11/15/2024 at inspectors request.  
Pressure well to 1310 psi. Hold for 15 min. Final pressure 1300 psi. -10 psi loss. OK  
Test witnessed by ECMC using chart on test truck.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Date Run: 11/17/2024 Doc [#693807901]

Page 4 of 5

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693807907	Inspection photos 11/15/2024	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6789885">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6789885</a>