

Inspection Photos

API: 043-06219

Operator: AUSCO PETROLEUM INC

Inspection Date: 11/14/2024



Inspection Photos



Photo 1. Facing northwest along the access road. There are check dams that are filled in and not maintained and erosion along the roadside.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. There are check dams where stormwater has eroded around the check dam. BMP maintenance is required.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 043-06219 | Date: 11/14/2024

Inspection Photos



Photo 3. Facing north toward the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 043-06219 | Date: 11/14/2024

Inspection Photos



Photo 4. Perennial vegetation is progressing in the interim reclamation area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 5. Facing west at the location. The dark brown vegetation is undesirable weeds that need to be controlled.



Inspection Photos



Photo 6. The weed debris around the equipment must be removed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 7. Facing toward the wellhead. The area around the equipment needs to be kept free of dry vegetation and debris.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 8. The open cellar at the wellhead needs to be covered or have an escape ramp for critters.



Inspection Photos



Photo 9. Facing north at the wellsite. The wattles at the red arrow are degraded and not maintained.

