

# Inspection Photos

API: 043-06229

Operator: AUSCO PETROLEUM INC

Inspection Date: 11/14/2024



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos



**Photo 1.** Facing northwest toward the location.



## Inspection Photos



**Photo 2.** The perennial vegetation is progressing well in the interim reclamation area. The fence around this area was removed but the white poles still remain.



## Inspection Photos



**Photo 3.** There are noxious weeds (Mullein) along the road near the well that will need to be controlled during the next growing season..




**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API: 043-06229 | Date: 11/14/2024

## Inspection Photos



**Photo 4.** There is a orange bucket of oil that needs to be removed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API: 043-06229 | Date: 11/14/2024