

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/18/2024

Submitted Date:

11/18/2024

Document Number:

696306955

FIELD INSPECTION FORM

Loc ID: 437321 Inspector Name: PETRIE, ERICA On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

ECMC Operator Number: 10508
Name of Operator: SELECT WATER SOLUTIONS LLC
Address: 12515 CARRIAGE WAY
City: OKLAHOMA CITY State: OK Zip: 73142

Contact Information:

Contact Name	Phone	Email	Comment
Ryan Dornbos	303-915-9074	Ryan@PetersonEnergyOperating.com	Contractor
Frazier, Thad	208-220-9534	TFrazier@selectenergy.com	All Inspections
Gabel, Kayla		kgabel@selectenergy.com	All Inspections
Green, Zach	405-206-5396	zgreen@selectenergy.com	All Inspections
		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437322	WELL	TA	04/01/2023	DSPW	123-39484	Weitzel 1	TA

General Comment:

This is a Field Observation of an MIT for Future UIC Injection Well.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 1		
Comment:	TA Wellhead - Flowline not yet ran out to Well		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 437322 Type: WELL API Number: 123-39484 Status: TA Insp. Status: TA

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: EPUP

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 05/02/2023

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: 160 Csg psi: 2286 BH psi: 0

Insp. Status: _____

Comment: Start Time: 9:40
Start PSI: T - 160, C - 2286, SC - 0
5 Mins: T - 160, C - 2287, SC - 0
10 Mins: T - 160, C - 2288, SC - 0
15 Mins: T - 160, C - 2289, SC - 0

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
This is a Field Observation of an MIT for Future UIC Injection Well.	petrie	11/18/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696306956	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6790530