

Inspection Photos

Location: QB ENERGY BJU/B26-496 Pad
Location ID: 479149
Date: 11/14/2024



Photo # 9054 Entrance to location



Photo # 9123 Location

Inspection Photos

Location: QB ENERGY BJU/B26-496 Pad

Location ID: 479149

Date: 11/14/2024



Nov 14, 2024 at 12:30:26 PM
+39.677149,-108.138557 ±4.73m
Parachute

Photo # 9055 Location



Nov 14, 2024 at 12:31:22 PM
+39.677455,-108.138602 ±4.73m
Parachute

Photo # 9056 Location

Inspection Photos
Location: QB ENERGY BJU/B26-496 Pad
Location ID: 479149
Date: 11/14/2024



Photo # 9063 Location



Photo # 9065 Location

Inspection Photos
Location: QB ENERGY BJU/B26-496 Pad
Location ID: 479149
Date: 11/14/2024



Photo # 9075 Location



Photo # 9108 Location

Inspection Photos
Location: QB ENERGY BJU/B26-496 Pad
Location ID: 479149
Date: 11/14/2024



Photo # 9116 Location




Photo # 9117 Location

Inspection Photos

Location: QB ENERGY BJU/B26-496 Pad

Location ID: 479149

Date: 11/14/2024



Photo # 9121 Location




Photo # 9129 NE corner of location

Inspection Photos

Location: QB ENERGY BJU/B26-496 Pad

Location ID: 479149

Date: 11/14/2024



Photo # 9130 NW corner of location



Photo # 9133 SW corner of location

Inspection Photos

Location: QB ENERGY BJU/B26-496 Pad

Location ID: 479149

Date: 11/14/2024



Nov 14, 2024 at 1:43:11 PM
+39.676933,-108.137959 ±4.73m
Parachute

Photo # 9134 SE corner of location



Nov 14, 2024 at 12:50:13 PM
+39.677684,-108.138092 ±4.74m
Parachute

Photo # 9073 Open ended piping/wildlife hazard/ available for entry by wildlife

Inspection Photos

Location: QB ENERGY BJU/B26-496 Pad

Location ID: 479149

Date: 11/14/2024



Photo # 9076 Open ended piping/wildlife hazard/ available for entry by wildlife



Photo # 9077 Open ended piping/wildlife hazard/ available for entry by wildlife

Inspection Photos

Location: QB ENERGY BJU/B26-496 Pad

Location ID: 479149

Date: 11/14/2024



Photo # 9079 Open ended piping/wildlife hazard/ available for entry by wildlife



Photo # 9080 Open ended piping/wildlife hazard/ available for entry by wildlife

Inspection Photos

Location: QB ENERGY BJU/B26-496 Pad

Location ID: 479149

Date: 11/14/2024



Photo # 9084 Open ended piping/wildlife hazard/ available for entry by wildlife



Photo # 9090 Open ended piping/wildlife hazard/ available for entry by wildlife

Inspection Photos

Location: QB ENERGY BJU/B26-496 Pad

Location ID: 479149

Date: 11/14/2024



Photo # 9091 Open ended piping/wildlife hazard/ available for entry by wildlife



Photo # 9100 Open ended piping/wildlife hazard/ available for entry by wildlife

Inspection Photos
Location: QB ENERGY BJU/B26-496 Pad
Location ID: 479149
Date: 11/14/2024



Photo # 9119 Open ended piping/wildlife hazard/ available for entry by wildlife



Photo # 9104 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location: QB ENERGY BJU/B26-496 Pad

Location ID: 479149

Date: 11/14/2024



Photo # 9105 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 9107 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location: QB ENERGY BJU/B26-496 Pad

Location ID: 479149

Date: 11/14/2024



Photo # 9141 Lack of stabilization/compaction on location/insufficient BMP's



Photo # 9148 Lack of stabilization/compaction on location/insufficient BMP's

Inspection Photos

Location: QB ENERGY BJU/B26-496 Pad

Location ID: 479149

Date: 11/14/2024



Photo # 9150 Lack of stabilization/compaction on location/insufficient BMP's



Photo # 9120 Debris

Inspection Photos
Location: QB ENERGY BJU/B26-496 Pad
Location ID: 479149
Date: 11/14/2024



Photo # 9128 Debris



Photo # 9132 Debris