

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/18/2024

Submitted Date:

11/18/2024

Document Number:

715201202**FIELD INSPECTION FORM**Loc ID 324872 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 37230Name of Operator: HALDE OIL INCAddress: 46321 HWY 24City: BURLINGTON State: CO Zip: 80807**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments7 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Shalberg, Greg	719-688-3547	gregshalberg@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213346	WELL	SI	03/01/2024	GW	061-06708	MAYER 12-2 1	PA

General Comment:

SE Compliance Specialist Brian Welsh conducted a Follow up Inspection from the P&A process

Well was plugged. Operator has 30 days to remove equipment from location and begin final reclamation process

Location				
Lease Road:				
Type	Access			
comment:	Dirt road through farm ground			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Lease sign where the tank used to be			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds across location			
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Ancillary equipment	# 3			corrective date
Comment:	Gas scrubber, solar powered cathodic rectifier, telemetry equipment			
Corrective Action:	Remove from location and begin final reclamation process			Date: <u>12/18/2024</u>
Type: Pump Jack	# 1			
Comment:	SM-Cyclo 160			
Corrective Action:	Remove from location and begin final reclamation process			Date: <u>12/18/2024</u>
Type: Vertical Separator	# 1			
Comment:	Vertical gas separator on west side of metal shed			
Corrective Action:	Remove from location and begin final reclamation process			Date: <u>12/18/2024</u>
Type: Gas Meter Run	# 1			
Comment:	Meter shed on northwest corner of location			
Corrective Action:	Remove from location and begin final reclamation process			Date: <u>12/18/2024</u>
Type: Compressor	# 1			
Comment:	Skid mounted gas powered booster compressor in metal shed			
Corrective Action:	Remove from location and begin final reclamation process			Date: <u>12/18/2024</u>

Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:	Remove from location and begin final reclamation process	Date:	12/18/2024
Type: Prime Mover	# 1		
Comment:	Arrow gas engine		
Corrective Action:	Remove from location and begin final reclamation process	Date:	12/18/2024

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	213346	Type:	WELL	API Number:	061-06708	Status:	SI	Insp. Status:	PA
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715201203	location photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6791303