

Inspection Photos

Location: QB ENERGY SGU-64S96W/23SWSW (M23-496)

Location ID: 335680

Date: 11/14/2024




Photo # 9155 Entrance to location

Photo # 9171 Location

Inspection Photos
Location: QB ENERGY SGU-64S96W/23SWSW (M23-496)
Location ID: 335680
Date: 11/14/2024



Photo # 9156 Location

Photo # 9164 Location

Inspection Photos

Location: QB ENERGY SGU-64S96W/23SWSW (M23-496)

Location ID: 335680

Date: 11/14/2024



Nov 14, 2024 at 2:18:30 PM
+39.681641,-108.142781 ±4.73m



Nov 14, 2024 at 2:19:49 PM
+39.681469,-108.143100 ±4.73m

Photo # 9167 Location

Photo # 9170 Location

Inspection Photos

Location: QB ENERGY SGU-64S96W/23SWSW (M23-496)

Location ID: 335680

Date: 11/14/2024



Photo # 9196 Location



Photo # 9198 Location

Inspection Photos

Location: QB ENERGY SGU-64S96W/23SWSW (M23-496)

Location ID: 335680

Date: 11/14/2024



Photo # 9184 NW corner of location



Photo # 9185 NE corner of location

Inspection Photos

Location: QB ENERGY SGU-64S96W/23SWSW (M23-496)

Location ID: 335680

Date: 11/14/2024



Photo # 9199 SW corner of location



Photo # 9182 Flow line heating insulation open ended/wildlife hazard available for entry by wildlife

Inspection Photos

Location: QB ENERGY SGU-64S96W/23SWSW (M23-496)

Location ID: 335680

Date: 11/14/2024



Photo # 9186 Loose barbed wire fencing/wildlife hazard



Photo # 9190 Loose barbed wire fencing/wildlife hazard

Inspection Photos

Location: QB ENERGY SGU-64S96W/23SWSW (M23-496)

Location ID: 335680

Date: 11/14/2024



Photo # 9194 Loose barbed wire fencing/wildlife hazard

Photo # 9195 Loose barbed wire fencing/wildlife hazard