

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2024

Submitted Date:

11/19/2024

Document Number:

716201249**FIELD INSPECTION FORM**Loc ID 336317 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Oxy		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271498	WELL	SI	07/01/2020	OW	123-22074	BARCLAY 4-27	TA
287865	WELL	SI	07/01/2020	GW	123-24430	BARCLAY 29-22	TA

General Comment:[This is a corrective action Wellhead audit.](#)[Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:		
Type	WEEDS	
Comment:	Weeds at wellheads.	
Corrective Action:	Comply with Rule 606.	Date: 11/27/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:		
Type	WELLHEAD	
Comment:	Pipe Panels	
Corrective Action:		Date:

Equipment:			corrective date
Type: Plunger Lift	# 0		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.199650,-104.769940
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:					
Corrective Action:					Date:
Venting:					
Yes/No					
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 271498

Type: WELL

API Number: 123-22074

Status: SI

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In

☒ Temporarily Abandoned

Reminder:

Comment: TA

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287865

Type: WELL

API Number: 123-24430

Status: SI

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In

☒ Temporarily Abandoned

Reminder:

Comment: TA

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<div>This is a corrective action Wellhead audit. Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.</div>	carlilec	11/19/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716201250	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6792144