

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2024

Submitted Date:

11/18/2024

Document Number:

707801227

FIELD INSPECTION FORM

Loc ID 335798	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: ECMC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202				Findings: 21 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265451	WELL	PR	03/01/2019	GW	045-09020	CHEVRON 22-7D	PR
265452	WELL	PR	03/01/2019	GW	045-09019	CHEVRON 23-7D	PR
265454	WELL	PR	08/01/2024	GW	045-09018	CHEVRON 13-7D	PR
265455	WELL	PR	03/01/2019	GW	045-09017	CHEVERON 14-7D	PR
265456	WELL	PR	03/01/2019	GW	045-09021	CHEVRON 24-7D	PR
291053	WELL	PR	03/01/2019	GW	045-14269	CHEVRON-MARATHON 12C-7D	PR
291054	WELL	PR	03/01/2019	GW	045-14270	CHEVRON 12D-7D	PR
291055	WELL	PR	03/01/2019	GW	045-14271	CHEVRON 13A-7D	PR
291056	WELL	PR	03/01/2019	GW	045-14272	CHEVRON 13C-7D	PR
291057	WELL	PR	03/01/2019	GW	045-14273	CHEVRON 13D-7D	PR
291058	WELL	PR	03/01/2019	GW	045-14274	CHEVRON 14A-7D	PR
291059	WELL	PR	03/01/2019	GW	045-14275	CHEVRON 23D-7D	PR
291060	WELL	PR	03/01/2019	GW	045-14276	CHEVRON 12A-7D	PR
291061	WELL	PR	03/01/2019	GW	045-14277	CHEVRON 11D-7D	PR
291075	WELL	PR	03/01/2019	GW	045-14291	CHEVRON 24B-7D	PR
291076	WELL	PR	03/01/2019	GW	045-14292	CHEVRON 24A-7D	PR

General Comment:

ECMC Inspection Report Summary

On Friday 11/15/2024, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus Chevron-66S96W 7NWSW, at Location # 335798 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Open ended piping for thawing out dump lines on tanks and separators with exhaust from trucks. Some valves on separators are missing caps.

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Open ended piping for thawing out dump lines on tanks and separators with exhaust from trucks. Some valves on separators are missing caps.		
Corrective Action:	Eliminate possibility of wildlife to enter open lines for thawing out dump lines with exhaust from trucks.		Date: 12/27/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 16		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 10		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 17		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 16		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID:	265451	Type:	WELL	API Number: 045-09020 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	265452	Type:	WELL	API Number: 045-09019 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	265454	Type:	WELL	API Number: 045-09018 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	265455	Type:	WELL	API Number: 045-09017 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	265456	Type:	WELL	API Number: 045-09021 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	291053	Type:	WELL	API Number: 045-14269 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	291054	Type:	WELL	API Number: 045-14270 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	291055	Type:	WELL	API Number: 045-14271 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

<u>Producing Well</u>				
Comment:	Producing			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	291056	Type:	WELL	API Number: 045-14272 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	291057	Type:	WELL	API Number: 045-14273 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	291058	Type:	WELL	API Number: 045-14274 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	291059	Type:	WELL	API Number: 045-14275 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	291060	Type:	WELL	API Number: 045-14276 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	291061	Type:	WELL	API Number: 045-14277 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	291075	Type:	WELL	API Number: 045-14291 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing			

Corrective Action:		Date:							
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	291076	Type:	WELL	API Number:	045-14292	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:				Date:					
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Retention Ponds				
		Sediment Traps				
		Check Dams				
		Ditches				

Comment: Limited storm water inspection due to snow cover

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707801232	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6792516