

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 23-25 Booster Station

Facility ID: 488423



Photo # 9883 From entrance to location



Photo # 9884 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 23-25 Booster Station

Facility ID: 488423



Photo # 9885 Location



Photo # 9886 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 23-25 Booster Station

Facility ID: 488423



Photo # 9887 Location



Photo # 9888 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 23-25 Booster Station

Facility ID: 488423



Photo # 9889 Location



Photo # 9890 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 23-25 Booster Station

Facility ID: 488423



Photo # 9891 Location



Photo # 9892 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 23-25 Booster Station

Facility ID: 488423



Photo # 9893 Debris



Photo # 9894 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 23-25 Booster Station

Facility ID: 488423



Photo # 9895 Debris



Photo # 9896 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 23-25 Booster Station

Facility ID: 488423



Photo # 9897 Tank lacks required labeling



Photo # 9898 Tank lacks required labeling



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 23-25 Booster Station

Facility ID: 488423



Photo # 9899 Tank lacks required labeling



Photo # 9900 Tank lacks required labeling

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 23-25 Booster Station

Facility ID: 488423



Photo # 9901 Open ended load line



Photo # 9902 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 23-25 Booster Station

Facility ID: 488423



Photo # 9903 Open ended load line




Photo # 9904 Tank label weathered & some required information is illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 23-25 Booster Station

Facility ID: 488423




Photo # 9905 Tank label weathered & some required information is starting to become illegible



Photo # 9906 Tank label weathered & some required information is starting to become illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 23-25 Booster Station

Facility ID: 488423



Photo # 9907 Tank battery lacks required signage



Photo # 9908 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 23-25 Booster Station

Facility ID: 488423



Photo # 9909 Location