

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2024

Submitted Date:

11/20/2024

Document Number:

707603365**FIELD INSPECTION FORM**Loc ID 332020 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269735	WELL	SI	01/01/2024	OW	123-21723	KREPS TRUST 34-6	PA

**General Comment:**

This is a **PLUGGED & ABANDONED WELL / WORKOVER / CEMENTING** inspection.

Well(s): 1: Plugged & Abandoned | PA.

Plugging Operations: Cementing; Cement-surface.

Battery: Inactive. Shut-down.

Inactive Battery SE corner GPS coordinates: 40.489739 / -104.465512

Well GPS coordinates: 40.509000 / -104.589780

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Adequate			
Corrective ActionL				Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	OTHER			
Comment:	Jobsite entrance & safety signage posted.			
Corrective Action:				Date:
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:	<input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Equipment:</b>				
Type: Plunger Lift	# 0			corrective date
Comment:	Plugged & Abandoned   PA. Equipment removed.			
Corrective Action:				Date:
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	269735	Type:	WELL	API Number:	123-21723	Status:	SI	Insp. Status:	PA
Cement									
Cement Contractor									
Contractor Name: Duco Services					Contractor Phone:				
Surface Casing									
Cement Volume (sx):					Circulate to Surface:				
Cement Fall Back:					Top Job, 1" Volume:				
Intermediate Casing									
Cement Volume (sxs):					Good Return During Job:				
Production Casing									
Cement Volume (sx):					Good Return During Job:				
Plugging Operations									
Depth Plugs(feet range): 2257'-0'					Cement Volume (sx): 117 sxs				
Good Return During Job:					Cement Type: Class "G" Neat 15.8#				
Comment: 2024/11/19: Plugging Operations: Cementing; cement-surface. 2024/11/19: JSA attached as photo to this report.  Workover Contractor: Ensign Energy Services Rig #349. Cement Contractor: Duco Services.  CREW READY, JSA, SM, SIP ( T:0, C:0, S:0 ) WELL STATIC.  WINTER START UP, PREP PUMP & LINES, CHECK GROUNDS.  EOT AT 2099' W/ 64 JTS 2-3/8" TBG, TI W/ 5 TAG JTS TO CIBP @ 2257'.  SM W/ DUCO CMTRS, RU, PUMP CIBP CAP CMT PLUG FROM 2257 - 2064'. 10 bb FW, FULL RETURNS, 3 bb CMT @ 15.8# ( 15sx NEAT G, 1.15 YIELD, 5.0 ga/sx ) 8 bb FW DISP, PLUG BALANCED.  POOH, LD 39 JTS, EOT @ 985'. TIE IN CMTRS, PUMP SFC TO SFC PLUG. 5 bb FW, FULL RETURNS, MIX & PUMP 22 bb CMT @ 15.8#, 2 bb CMT TO SFC. POOH W/ BALANCE OF TBG, TOP OFF WELL W/ 2 bb CMT @ 15.8#, CMT AT SFC, RD CMTRS. TOTAL CMT MIXED FOR SFC PLUG: 24 bb ( 117 sx NEAT G, 1.15 YIELD, 5.0 ga/sx ).  RD FLOOR, ND BOP & CLEAN ALL EQ. B/O 3k WELLHEAD, MU 4-1/2" CSG SWAGE W/ BALL VALVE, SECURE WELL W/ P&A TAG, GREEN LOCKS. RD, RACK HARDLINE.  ** CMT MW: 7.1 ph, < 200 CHLORIDES, 72*									
Corrective Action:					Date:				
Workover									
Comment: 2024/11/19: Plugging Operations: Cementing; cement-surface. 2024/11/19: JSA attached as photo to this report.  Workover Contractor: Ensign Energy Services Rig #349. Cement Contractor: Duco Services.  Reference: Form 6N on file. Notice of Intent to Abandon date: 11/06/2024. Approved. Form 42 on file. Notice of MIRU. Start Date: 11/15/2024. Approved. Form 42 on file. Notice of Plugging Operations. Start Date: 11/15/2024. Approved.									

Corrective Action:		Date:	
--------------------	--	-------	--

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p><b>CECMC Inspection Report Synopsis:</b></p> <p>On TUE 11/19/2024 at approximately 10:27 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: PDC ENERGY INC  Location Name: KREPS TRUST-66N64W/6SWSE  Location ID: 332020  Well Name(s) &amp; API:  Reference:  See "Inspected Facilities" section on page 1 of this Field Inspection Report.  Location County: Weld County, Colorado  Weather: Mostly Sunny, damp from prior storm.</p> <p>While there, I observed:  Well(s): 1: Plugged &amp; Abandoned   PA.  Plugging Operations: Cementing; Cement-surface.  Battery: Inactive. Shut-down.  Inactive Battery SE corner GPS coordinates: 40.489739 / -104.465512  Well GPS coordinates: 40.509000 / -104.589780</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	11/20/2024

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603366	Site photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6794452">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6794452</a>